



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

| | |
|--|---------------------------|
| INCOME INSURANCE LTD | Ref: NS/INC22007555/Tvce2 |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | Date: 03-10-2022 |
| | Code: INC4 |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | FBQ 9256G | Veh. Inspected | SHA 7019B |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1183189-002 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 04/08/2022 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | HYUNDAI IONIQ | c.c | 1580 |
| Engine No. | HIDDEN | Year of Reg. | 2019 |
| Chassis No. | KMHC851CVLU186634 | Colour | BLUE |
| Odometer | 237976 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|-----------|---------|
| R/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm |
| L/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm |
| R/H Rear Tyre | 195/65 R15 | WEST LAKE | 6 mm |
| L/H Rear Tyre | 195/65 R15 | WEST LAKE | 6 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 04/08/2022 | Inspection Date | 04/08/2022 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|-----------------------|