



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6505E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRACKED	481.10	481.10
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER UPPER MOULDING	TO REPAIR SEE LABOUR	368.50	-
1	FRT FENDER SHIELD RH	NOT NECESSARY	588.80	-
1	FRT WHEEL CAP RH	CRACKED	346.40	346.40
1	HEADLAMP RH	NOT NECESSARY	2,110.30	-
1	DAYLIGHT RH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE RH	NOT NECESSARY	93.45	-
	LESS 20% DISCOUNT		-930.61	-169.90
			3,722.44	679.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT WESTLAKE TYRE RH (SN) (60%)	CUT	216.00	129.60
			216.00	129.60
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER UPPER MOULDING.		400.00	350.00
	SPRAY PAINTING.		600.00	250.00
	CHECK WIRINGS.	NOT NECESSARY	40.00	-
	WHEEL ALIGNMENT.		120.00	80.00
			1,160.00	680.00
<b>GRAND TOTAL</b>			<b>5,098.44</b>	<b>1,489.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,200.00</b>

Report Ref No. NS/INC22007558/Tnce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.