

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22007567/APA3Q2**Date:** 29/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100488032
<b>Claimant Vehicle No :</b>	SLR6633Y	<b>Insured Vehicle No :</b>	SLH3219H
Date of Loss:	06/08/2022	Nature of Claim:	TP
		Claim No:	2739852179SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR6633Y</b>	Engine No:	F2871716B38B15A
Make & Model:	BMW 318I, 1.5 SEDAN LED NAV (A)	Chassis No:	WBA8E36020NU80345
Reg. Date:	24/08/2017 (Man. Year: 2017)	Odometer:	39164 km
Colour:	Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,969.50	6,214.44	1,755.06	22.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	680.00	370.00	35.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,019.50</b>	<b>6,894.44</b>	<b>2,125.06</b>	<b>23.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,019.50</b>	<b>5,500.00</b>	<b>3,519.50</b>	<b>39.02</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>Nett Liability (S\$)</b>		<b>5,800.00</b>		

INSPECTION

Date of Assignment:	08/08/2022	
Date Inspected:	08/08/2022	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,388.80 F	*1,388.80 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Not Necessary	75.80 F	*- FL
4	1		*FRONT BUMPER SPONGE	Deformed	188.20 F	*188.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	558.00 F	*- FL
6	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	365.20 F	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	110.40 F	*110.40 FL
8	1		*FRONT BUMPER LOWER DIFFUSER	Deformed	1,498.60 F	*1,498.60 FL
9	1		*FRONT BUMPER SENSOR	Damaged	250.40 F	*250.40 FL
10	1		*HEADLAMP RH	Cracked	3,435.20 F	*3,435.20 FL
11	1		*HEADLAMP LOWER MOUNTING RH	Not Necessary	68.90 F	*- FL
					<b>Sub Total (\$\$)</b>	<b>7,969.50      6,901.60</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00      687.16</b>
					<b>Total Parts (\$\$)</b>	<b>7,969.50      6,214.44</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
4	TO PERFORM DIANOGSTIC TEST	New	200.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,050.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >