

TPA16.
Cecilia

SLR6633Y 2017 August.

BMW 318i 1499cc

WBASE36020XU80345.

Front Bumper Deformed	1388.80 ✓
Front Bumper Clips. New	30(SN). ✓
Front Bumper Side Holder RH. ^{new} _{new}	75.80. +
Front Bumper Sponge. Deformed	188.20 ✓
Front Bumper Reinforcement. ^{new} _{new}	558 +
Front Bumper Fog Lamp RH. ^{new} _{new}	365.20. +
Front Bumper Fog Lamp Cover RH. cut	110.40. ✓
Front Bumper lower Diffuser. Deformed	1498.60. ✓
Front Bumper Sensor Damaged.	250.40. ✓
Headlamp RH. Cracked	3435.20 ✓
Headlamp lower Mounting RH. ^{new} _{new}	68.90. +

6871.60

6184.44

S.N. 30

SLR 6633Y.

Panel Bending
Spray Painting.
Wiring.

To perform diagnostic test.

~~400~~ 300 1
~~400~~ 250
~~50~~ 30 680
~~200~~ 100

total: 6894.44

L/S: 5.5K.

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5.5K