

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22007569/KPA3Q2**Date:** 01/09/2022**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000483  
**Claimant Vehicle No :** SJU2486P **Insured Vehicle No :** SLH6204E  
 Date of Loss: 29/07/2022 Nature of Claim: TP Claim No: OWAISCL2022-0000147

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJU2486P**  
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY002318  
 Reg. Date: 25/11/2009 (Man. Year: 2009) Chassis No: MR053HY9305140070  
 Colour: Metallic Silver Odometer: 315375 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15  
 Front Left Side: Airvo 8 mm Rear Left Side: West Lake 5 mm  
 Front Right Side: Airvo 8 mm Rear Right Side: West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,736.62	2,107.84	2,628.78	55.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,270.00	930.00	42.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,936.62</b>	<b>3,377.84</b>	<b>3,558.78</b>	<b>51.30</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,936.62</b>	<b>2,700.00</b>	<b>4,236.62</b>	<b>61.08</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,957.45</b>		

**INSPECTION**

Date of Assignment: 08/08/2022  
 Date Inspected: 10/08/2022 Inspected At: Ngs Motorsport Pte Ltd - Ang Mo Kio (HQ)  
 Blk 10 Ang Mo Kio Ind Pk 2A, #02-01 AMK  
 AutoPoint  
 Singapore 568047  
 Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2022)
<b>Parts:</b> 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJU2486P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	697.50 FL	*658.70 FL
2	2		*REAR BOOT HINGE RH/LH	Repair	99.40 FL	*- FL
3	1		*REAR BOOT INNER LOCK	Dented	146.80 FL	*146.80 FL
4	1		*REAR BUMPER	Buckled	534.40 FL	*534.40 FL
5	1		*REAR BUMPER RETAINER UPP RH/LH	N/S Distorted	97.40 FL	*48.70 FL
6	2		*REAR BUMPER RETAINER LOW RH/LH	Serviceable	211.00 FL	*- FL
7	1		*TAILLAMP RH/LH	N/S Cracked	552.40 FL	*276.20 FL
8	1		*GASKET ,TAILLAMP RH/LH	N/S Necessary	78.92 FL	*39.46 FL
9	4		*CLIPS ,TAILLAMP RH/LH	Not Necessary	34.00 FL	*- FL
10	1		*WEATHERSTRIP ,RR TRUNK (50%)	Cut	107.03 FS	*71.35 FS
11	1		*LUGGAGE COMPARTMENT PANEL	Repair	639.50 FL	*- FL
12	1		*LUGGAGE COMPARTMENT BOARD	Serviceable	155.90 FL	*- FL
13	1		*END PANEL	Bent	592.20 FL	*516.20 FL
14	1		*GARNISH ,END PANEL	Cracked	226.83 FL	*135.00 FL
15	1		*EMBLEM E	Necessary	38.40 FL	*38.40 FL
16	1		*EMBLEM VIOS	Necessary	54.80 FL	*54.80 FL
17	14		*CLIPS ,TRUNK TRIM	Not Necessary	70.00 FS	*- FS
18	2		*FRT & RR RH SPORT RIM	Serviceable	1,160.00 FS	*- FS
19	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,776.48</b>	<b>2,720.01</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,039.86	612.17
<b>Total Parts (S\$)</b>	<b>4,736.62</b>	<b>2,107.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT /ATTACHMENT STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL REPLACE DAMAGED PART REFIT INTO PORSITION	New	1,000.00	600.00
2	TO TRANSFER REAR BOOT LID MECHANISM	New	150.00	50.00
3	TO SPRAY PAINTING	New	1,000.00	600.00
4	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>2,200.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >