

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007571/AVCE2**Date:** 09/12/2022**REFERENCE**

Insured/Claimant: MAK KIAN SOON BENJAMIN(MAI JIANSHUN, BENJAMIN)

Policy No: 1800143872

Date of Loss: 01/08/2022

Nature of Claim: OD

Claim No: 3975687128SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKV939X**

Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)

Engine No: CVK071541

Reg. Date: 20/12/2018 (Man. Year: 2018)

Chassis No: WAUZZZF46KN000633

Colour: Blue

Odometer: 41691 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$128,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,135.00	2,329.20	23,805.80	91.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,772.00	1,722.00	3,050.00	63.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,907.00	4,051.20	26,855.80	86.89
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	30,107.00	3,251.20	26,855.80	89.20
+ GST 7.00/7.00% (S\$)	2,107.49	227.58	1,879.91	89.20
Nett Amount (S\$)	32,214.49	3,478.78	28,735.71	89.20

INSPECTION

Date of Assignment: 10/08/2022

Date Inspected: 08/08/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,377.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER LOWER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	2		*FRONT RADIATOR AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,478.00 FS	*1,182.40 FS
8	2		*RADIATOR AIR GUIDE GRILLE - LH / RH	Not Necessary	302.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
10	1		*FRONT BUMPER CARRIER	Dented	899.00 FS	*719.20 FS
11	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
15	1		*FRONT BUMPER BRACKET	Not Necessary	154.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT	Damaged	64.00 FS	*25.60 FS
17	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
18	1		*FRONT PARKING AID SENSOR - INNER / OUTER (2PCS)	Missing (1pc only)	531.00 FS	*212.00 FS
19	4		*FRONT BUMPER PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
20	1		*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
21	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
22	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
23	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
24	2		*HEADLIGHT - LH / RH	Not Necessary	16,588.00 FS	*- FS
25	2		*LIFT CYLINDER - LH / RH	Not Necessary	462.00 FS	*- FS
26	2		*LIFT CYLINDER BRACKET	Not Necessary	14.00 FS	*- FS
27	1		*LIFT CYLINDER HOSE	Not Necessary	107.00 FS	*- FS
28	2		*FRONT RADIATOR AIR GUIDE - LH / RH	Not Necessary	64.00 FS	*- FS
29	2		*FRONT RADIATOR AIR GUIDE - LH / RH	Not Necessary	28.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
31	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
33	1		*OUTER TEMP SENSOR BRACKET (Supplementary)	Necesaary	21.00 FS	*16.32 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 26,135.00 2,329.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BONNET RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,772.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >