

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22007572/EPA3Q2**Date:** 10/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_03

Claimant Vehicle No : SMF3151S **Insured Vehicle No :** SNC7652R

Date of Loss: 28/07/2022 Nature of Claim: TP Claim No: MFL2022D0004130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF3151S**
 Make & Model: KIA CERATO, 1.6 SX (A) Engine No: G4FGJH709917
 Reg. Date: 02/11/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5019051
 Colour: Grey Odometer: 53153 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,327.85	10,040.85	1,287.00	11.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,730.00	90.00	4.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,147.85	11,770.85	1,377.00	10.47
Approved Total (Overridden) (\$\$)		9,400.00		
Nett Amount (\$\$)	13,147.85	9,400.00	3,747.85	28.51
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 10/08/2022

Date Inspected: 10/08/2022 Inspected At: Charn's Customcraft (HQ)
Block 1010 Bukit Merah Lane 3, #01-105
Singapore 159724

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
Parts:	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF3151S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Dented	944.00 FL	*944.00 FL
2	1	*BONNET SPONGE	Crushed	136.00 FL	*136.00 FL
3	13	*BONNET SPONGE CLIPS	Necessary	45.50 FL	*45.50 FL
4	1	*BONNET HINGE LHS	Bent	55.00 FL	*55.00 FL
5	1	*BONNET HINGE RHS	Bent	55.00 FL	*55.00 FL
6	1	*BONNET LOCK	Bent	80.00 FL	*80.00 FL
7	1	*FRONT BUMPER	Broken	468.00 FL	*468.00 FL
8	1	*FRONT BUMPER LOGO	Necessary	35.00 FL	*35.00 FL
9	1	*FRONT BUMPER GRILLE (TOP)	Broken	220.00 FL	*220.00 FL
10	1	*FRONT BUMPER GRILLE CHROME	Broken	125.00 FL	*125.00 FL
11	1	*FRONT BUMPER TOWING COVER	Crushed	35.00 FL	*35.00 FL
12	1	*FRONT BUMPER SIGNAL LHS	Cut	185.00 FL	*185.00 FL
13	1	*FRONT BUMPER SIGNAL RHS	Cut	185.00 FL	*185.00 FL
14	1	*FRONT BUMPER SIGNAL LAMP SOCKET LHS (NPA)	Torn	0.00 FL	*- FL
15	1	*FRONT BUMPER FOGLIGHT RHS	Broken	245.00 FL	*245.00 FL
16	1	*FRONT BUMPER FOGLIGHT COVER LHS	Cut	80.00 FL	*80.00 FL
17	1	*FRONT BUMPER FOGLIGHT COVER RHS	Cut	80.00 FL	*80.00 FL
18	1	*FRONT BUMPER SIDE GRILLE LHS	Cut	180.00 FL	*180.00 FL
19	1	*FRONT BUMPER SIDE GRILLE RHS	Cut	180.00 FL	*180.00 FL
20	1	*FRONT BUMPER LOWER CENTER GRILLE	Broken	360.00 FL	*360.00 FL
21	1	*FRONT BUMPER LOWER CENTER GRILLE PARKING SENSOR LHS	Broken	160.00 FL	*160.00 FL
22	1	*FRONT BUMPER LOWER CENTER GRILLE PARKING SENSOR RHS	Broken	160.00 FL	*160.00 FL
23	1	*FRONT BUMPER LOWER SPOILER (NPA)	*Check	0.00 FL	*- FL
24	1	*FRONT BUMPER LOWER SEAL	Cut	70.00 FL	*70.00 FL
25	1	*FRONT BUMPER UNDER COVER	Crushed	160.00 FL	*160.00 FL
26	8	*FRONT BUMPER UNDER COVER CLIPS	Necessary	28.00 FL	*28.00 FL
27	10	*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
28	1	*FRONT BUMPER SPONGE	Broken	135.00 FL	*135.00 FL
29	1	*FRONT BUMPER REINFORCEMENT	Dented	355.00 FL	*355.00 FL
30	1	*FRONT BUMPER FOLIGHT BULB RHS	Broken	15.00 FL	*15.00 FL
31	1	*FRONT BUMPER TOP GARNISH	Broken	65.00 FL	*65.00 FL
32	1	*FRONT BUMPER LOWER BEAM	Broken	135.00 FL	*135.00 FL
33	1	*PARKING SENSOR WIRE HARNESS	Torn	185.00 FL	*185.00 FL
34	1	*HEADLAMP LHS	Broken	1,450.00 FL	*1,450.00 FL
35	1	*HEADLAMP RHS	Broken	1,450.00 FL	*1,450.00 FL
36	1	*A/C CONDENSER	Dented	780.00 FL	*780.00 FL
37	1	*A/C OUTER TEMPT SENSOR	*Check	70.00 FL	*- FL
38	1	*RADIATOR	*Check	550.00 FL	*- FL
39	1	*RADIATOR FAN MOTOR ASSY	*Check	450.00 FL	*- FL
40	1	*RADIATOR TOP HOSE	*Check	35.00 FL	*- FL
41	1	*RADIATOR TOP HOSE JOINT	*Check	135.00 FL	*- FL
42	1	*RADIATOR SIDE GARNISH LHS	Crushed	35.00 FL	*35.00 FL
43	1	*RADIATOR SIDE GARNISH RHS	Crushed	35.00 FL	*35.00 FL
44	1	*AIR DUCT	Broken	80.00 FL	*80.00 FL
45	1	*AIR FILTER LOWER CASING	*Check	105.00 FL	*- FL
46	1	*BATTERY UNDER TRAY	*Check	85.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SUPPORT PANEL	Broken	550.00 FL	*550.00 FL
48	1		*THROTTLE BODY	Broken	780.00 FL	*780.00 FL
49	1		*FRONT NO PLATE	Bent	35.00 FS	*35.00 FS
50	1		*RADIATOR COOLANT	Necessary	35.00 FS	*35.00 FS
51	1		*SET BODY STICKER	Necessary	650.00 FS	*650.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,506.50	11,076.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,178.65	1,035.65
Total Parts (\$\$)	11,327.85	10,040.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE ,REPLACE A/C CONDENSER & FITTINGS INCLUSIVE REFILL GAS	New	100.00	100.00
2	CHECK WIRING FUNCTION	New	40.00	30.00
3	REMOVE NECESSARY PARTS JACKING ,PANEL BEATING ,REPAIR AND STRAIGHTEN FRONT INNER PANEL ,FRONT FENDERS LHS/RHS INCLUSIVE REPLACING THE ABOVE	New	880.00	800.00
4	PUTTY AND RESPRAY FRONT SUPPORT PANEL ,FRONT BONNET ,FRONT FENDERS LHS /RHS ,FRONT BUMPER AND AFFECTED AREAS	New	800.00	800.00
Gross Labour Cost (S\$)			1,820.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >