



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9598H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	503.04	503.04
1	REAR BUMPER CENTRE MOULDING	NOT NECESSARY	654.96	-
1	REAR BUMPER EXTENSION RH	NOT NECESSARY	232.00	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	112.70	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	TAILLAMP UPPER RH	NOT NECESSARY	557.90	-
1	TAILLAMP LOWER RH	NOT NECESSARY	570.00	-
	LESS 25% DISCOUNT		-663.15	-131.26
			1,989.45	393.78
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTINGS.	NOT NECESSARY	40.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
			860.00	640.00
GRAND TOTAL			2,849.45	1,033.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				850.00

Report Ref No. NS/INC22007574/Gvcm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.