



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6619X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER OUTER MIRROR LH	TO REPAIR SEE LABOUR	141.90	-
1	MIRROR ASSY OUTER REAR VI	BROKEN	1,390.10	1,390.10
1	EMBLEM SIDE PANEL (HYBRID	NOT NECESSARY	86.50	-
	LESS 25% DISCOUNT		-404.63	-347.53
			1,213.87	1,042.57
	<u>NETT ITEMS</u>			
1	XX APP LOGO REAR DOOR L/R (N)	NECESSARY	80.00	80.00
1	FUEL TANK LID (PETROL ONL (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-11.00	-11.00
			99.00	99.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF COVER		700.00	350.00
	OUTER MIRROR LH.			
	SPRAYPAINT CHARGE.		800.00	500.00
	CHECK ALL WIRING.	NOT NECESSARY	50.00	-
			1,550.00	850.00
GRAND TOTAL			2,862.87	1,991.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. NS/INC22007575/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.