9/28/22, 4:53 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22007580/EQCQ2 Our File No:

28/09/2022 Date:

Odometer:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMB1SNA00016422101

TP

Claimant Vehicle

SKV9856S

Insured Vehicle No:

CB8389E

Date of Loss:

Reg. Date:

No:

07/08/2022

Nature of

Claim:

Claim SNM22D205524/C02/KHONGLH

CJZ620630

159230 km

WVWZZZAUZFW353899

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKV9856S Reg No:

VOLKSWAGEN GOLF, 1.2 (A7) TSI (A) Make & Model:

Engine No: 13/10/2015 (Man. Year: 2015) Chassis No:

Colour: Silver

Engine Capacity: 1197 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Rear Left Side: Dunlop 5 mm Dunlop 5 mm Front Right Side: Rear Right Side: Dunlop 5 mm Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,222.93	3,522.41	1,700.52	32.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,120.00	4,840.00	3,280.00	40.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,342.93	8,362.41	4,980.52	37.33
+ GST 7.00/7.00% (S\$)	934.01	585.37	348.64	37.33
Nett Amount (S\$)	14,276.94	8,947.78	5,329.16	37.33

INSPECTION

Date Inspected:

Date of Assignment: 23/09/2022

Volkswagen Group Singapore Pte Ltd

11/08/2022 Inspected At: 247 ALEXANDRA ROAD

Singapore 159934

Estimated Period of Repair: 6.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

		_			
\mathbf{H}	ים'	\mathbf{c}	re	n	ഫ
1	. 🖵	ᆫ	ᆫ	יוו	-

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2022)

Parts: 144 VOLKSWAGEN GOLF 1.2 (A7) TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV9856S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GAS-FILLED STRUT BONNET ABSORBER	Not Necessary	140.57 FS	*-FS
2	1		*COVER FOR BUMPER PRIMED	Broken	1,375.68 FS	*1,375.68 FS
3	1		*GUIDE PIECE LHS BUMPER SIDE BRACKET	Not Necessary	26.71 FS	*-FS
4	1		*GUIDE PIECE RHS BUMPER SIDE BRACKET	Broken	26.71 FS	*26.71 FS
5	1		*SUPPORT PART RHS BUMPER INNER BRACKET	Broken	59.69 FS	*59.69 FS
6	1		*GUIDE BUMPER CTR BRACKET	Not Necessary	67.00 FS	*-FS
7	1		*FOAM INSERT	Not Necessary	53.12 FS	*-FS
8	1		*IMPACT BEAM REINFORCEMENT	Not Necessary	770.01 FS	*-FS
9	1		*RADIATOR GRILLE SATIN BLA	Cut	581.98 FS	*581.98 FS
10	1		*COOLING AIR GRILL SATIN B BUMPER CTR LOWER GRILLE	Not Necessary	174.25 FS	*-FS
11	1		*COOLING AIR GRILL SATIN B RHS FOG LAMP GRILLE (LOWER) Not Necessary	106.57 FS	*-FS
12	1		*COVER PART FOR BUMPER SAT RHS FOG LAMP GRILLE (UPPER)	Not Necessary	32.27 FS	*-FS
13	1		*TWIN HALOGEN HEADLAMPS	Cut	781.06 FS	*781.06 FS
14	1		*FLAT CONTACT HOUSING H/LAMP WIRE HOUSING	Not Necessary	22.76 FS	*-FS
15	1		*FENDER RH	Dented	655.47 FS	*655.47 FS
16	1		*CROSS SUPPORT RHS FENDER BRACKET	Necessary	36.54 FS	*36.54 FS
17	2		*RIVETTED CAP NUT	Necessary	5.28 FS	*5.28 FS
18	1		*WHEELHOUSE LINER RHS FENDER LINER (UPPER)	Not Necessary	199.41 FS	*-FS
19	1		*WHEELHOUSE LINER RHS FENDER LINER (LOWER)	Not Necessary	107.85 FS	*-FS
F=Fra	inchise	part. S=S	SpcNett.	Total Parts (S\$)	5,222.93	3,522.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	3,360.00	1,680.00
2	SPRAY PAINT	New	4,000.00	2,400.00
3	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
		Gross Labour Cost (S\$)	8,120.00	4,840.00
	Report was unsub	mitted during this print-out.		

< END OF ESTIMATES >