

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22007581/EQCQ2**Date:** 29/09/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMW1586U **Insured Vehicle No :** SFW2375M

Date of Loss: 29/07/2022 Nature of Claim: TP Claim No: DMPC2200327H.02/GK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW1586U**

Make & Model: SKODA OCTAVIA, 1.4 AMBITION TSI (A) Engine No: CZDA64930

Reg. Date: 04/11/2020 (Man. Year: 2019) Chassis No: TMBBC7NEXL0043438

Colour: Black Odometer: 23597 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,238.23	392.78	1,845.45	82.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	2,400.00	2,480.00	50.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,118.23	2,792.78	4,325.45	60.77
+ GST 7.00/7.00% (S\$)	498.28	195.49	302.79	60.77
Nett Amount (S\$)	7,616.51	2,988.27	4,628.24	60.77

INSPECTION

Date of Assignment: 08/08/2022

Date Inspected: 12/08/2022 Inspected At: Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2022)

Parts: 143 SKODA OCTAVIA 1.4 AMBITION TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMW1586U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR FRONT BUMPER	Repair	1,352.70 FS	*- FS
2	2		*SENSOR BRACKET	Not Necessary	26.00 FS	*- FS
3	2		*SENSOR BRACKET	Not Necessary	26.00 FS	*- FS
4	4		*SEAL RING SATIN BLACK	Not Necessary	5.84 FS	*- FS
5	1		*2K-PLASTIC ADHESIVE	Not Necessary	85.94 FS	*- FS
6	1		*BONDING AGENT FOR PLASTIC	Not Necessary	68.85 FS	*- FS
7	1		*COVER FOR LHF FOG LAMP COVER	Cut	41.04 FS	*41.04 FS
8	1		*COOLING AI BUMPER GRILL	Not Necessary	119.29 FS	*- FS
9	1		*END PLATE BUMPER LOWER CENTER GRILL	Not Necessary	160.83 FS	*- FS
10	1		*HALOGEN FO LHF FOG LAMP	Cut	351.74 FS	*351.74 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,238.23** **392.78**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,520.00	840.00
2	SPRAY PAINTING	New	1,600.00	800.00
3	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (\$\$)			4,880.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >