

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22007585/TVY3E2**Date:** 22/11/2022**REFERENCE**

Insured/Claimant:	HWA SENG BUILDER PTE LTD	Policy No:	DMFG22005172
Date of Loss:	05/08/2022	Nature of Claim:	OD
		Claim No:	CDMFG22001587

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC719C	Engine No:	HR12185104B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0972254
Reg. Date:	29/04/2016 (Man. Year: 2016)	Odometer:	154765 km
Colour:	Grey		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,418.50	15,121.50	2,297.00	13.19
Miscellaneous Items	120.00	40.00	80.00	66.67
Labour	1,370.00	1,130.00	240.00	17.52
Paintwork Labour	1,200.00	1,100.00	100.00	8.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,108.50	17,391.50	2,717.00	13.51
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,508.50	16,791.50	2,717.00	13.93
+ GST 7.00/7.00% (S\$)	1,365.60	1,175.41	190.19	13.93
Nett Amount (S\$)	20,874.10	17,966.91	2,907.19	13.93

INSPECTION

Date of Assignment:	08/08/2022	Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	10/08/2022	Inspected At:	Kan Fook Sing Motor Workshop (Defu)
			No. 61 Defu Lane 12
			Singapore 539147
Estimated Period of Repair:	9.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC719C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STEERING AIR BAG (WCP)	Activated	1,500.00 F	*1,500.00 F
2	1		*STEERING AIR BAG WIRE (WCP)	Activated	180.00 F	*180.00 F
3	1		*DASHBOARD (NPA)	Deformed	-	*- F
4	1		*DASHBOARD AIR BAG (WCP)	Activated	2,200.00 F	*2,200.00 F
5	1		*AIR BAG ECU (WCP)	Activated	-	*1,400.00 F
6	1		*AIR BAG SENSOR RH (WCP)	Not Necessary	350.00 F	*- F
7	1		*AIR BAG SENSOR LH (WCP)	Activated	350.00 F	*600.00 F
8	1		*SEAT BELT RH (WCP)	Activated	600.00 F	*600.00 F
9	1		*SEAT BELT LH (WCP)	Not Necessary	600.00 F	*- F
10	1		*FRONT WIPER CORNER GARNISH RH (WCP)	Not Necessary	30.00 F	*- F
11	1		*FRONT WIPER CORNER GARNISH LH (WCP)	Not Necessary	30.00 F	*- F
12	1		*FRONT BONNET (WCP)	Bent	450.00 F	*450.00 F
13	1		*FRONT BONNET LOCK (WCP)	Bent	80.00 F	*80.00 F
14	1		*FRONT BONNET HINGE RH (WCP)	Bent	45.00 F	*45.00 F
15	1		*FRONT BONNET HINGE LH (WCP)	Bent	45.00 F	*45.00 F
16	1		*FRONT BONNET STOPPER RH (WCP)	Missing	30.00 F	*15.00 F
17	1		*FRONT BONNET STOPPER LH (WCP)	Missing	30.00 F	*15.00 F
18	1		*FRONT SUPPORT PANEL (WCP)	Bent	250.00 F	*250.00 F
19	1		*FRONT SUPPORT GARNISH (WCP)	Deformed	180.00 F	*180.00 F
20	1		*FRONT LOWER MEMBER (WCP)	Not Necessary	220.00 F	*- F
21	1		*FRONT FENDER RH (WCP)	Bent	320.00 F	*320.00 F
22	1		*FRONT FENDER LH (WCP)	Bent	320.00 F	*320.00 F
23	1		*FRONT FENDER SHIELD RH (WCP)	Not Necessary	95.00 F	*- F
24	20		*FRONT FENDER SHIELD CLIP (WCP)	Necessary	50.00 F	*40.00 F
25	1		*FRONT FENDER 1/4 GLASS MOULDING RH (WCP)	Not Necessary	200.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT FENDER 1/4 GLASS MOULDING LH (WCP)	Not Necessary	200.00 F	*- F
27	1		*FRONT GRILLE (WCP)	Cracked	210.00 F	*210.00 F
28	1		*FRONT EMBLEM (WCP)	Cracked	50.00 F	*55.00 F
29	1		*FRONT HEADLAMP RH (WCP)	Cracked	1,200.00 F	*450.00 F
30	1		*FRONT HEADLAMP LH (WCP)	Cracked	1,200.00 F	*450.00 F
31	1		*FRONT BUMPER (WCP)	Deformed	350.00 F	*350.00 F
32	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Deformed	30.00 F	*30.00 F
33	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Deformed	30.00 F	*30.00 F
34	1		*FRONT BUMPER FOAM (WCP)	Cracked	-	*150.00 F
35	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	250.00 F	*250.00 F
36	1		*FRONT BUMPER REINFORCEMENT BRACKET RH (WCP)	Bent	220.00 F	*185.00 F
37	1		*FRONT BUMPER REINFORCEMENT BRACKET LH (WCP)	Bent	220.00 F	*185.00 F
38	1		*FRONT BUMPER TOW COVER (WCP)	Cut	-	*35.00 F
39	10		*FRONT BUMPER CLIP (WCP)	Necessary	25.00 F	*25.00 F
40	1		*HORN (WCP)	Not Necessary	80.00 F	*- F
41	1		*AIR CON CONDENSER (WCP)	Bent	480.00 F	*125.00 F
42	1		*AIR CON LIQUID PIPE (WCP)	Not Necessary	120.00 F	*- F
43	1		*AIR CON SUCTION HOSE	Bent	250.00 F	*100.00 FS
44	1		*AIR CON DISCHARGE HOSE	Bent	250.00 F	*100.00 FS
45	1		*RADIATOR (WCP)	Bent	380.00 F	*380.00 F
46	1		*RADIATOR HOSE TOP (WCP)	Not Necessary	40.00 F	*- F
47	1		*RADIATOR HOSE LOWER (WCP)	Not Necessary	40.00 F	*- F
48	1		*RAIDATOR TOP MOUNTING RH (WCP)	Not Necessary	25.00 F	*- F
49	1		*RAIDATOR TOP MOUNTING LH (WCP)	Not Necessary	25.00 F	*- F
50	1		*RADIATOR FAN ASSY (WCP)	Cracked	320.00 F	*320.00 F
51	1		*SPARE TANK (WCP)	Deformed	70.00 F	*70.00 F
52	1		*WASHER TANK (WCP)	Deformed	125.00 F	*125.00 F
53	1		*INTAKE MANIFOLD (WCP)	Cracked	-	*600.00 F
54	1		*AIR CLEANER BOX (WCP)	Cracked	-	*330.00 F
55	1		*AIR CLEANER HOSE (WCP)	Damaged	150.00 F	*140.00 F
56	1		*ALTERNATOR (NPA)	Not Necessary	-	*- F
57	1		*ENGINE MOUNTING RH (WCP)	Bent	195.00 F	*180.00 F
58	1		*ENGINE MOUNTING LH (WCP)	Not Necessary	85.00 F	*- F
59	1		*ENGINE MOUNTING RR (WCP)	Not Necessary	80.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
60	1		*FRONT SIDE MIRROR RH (WCP)	Not Necessary	330.00 F	*- F
Supplementary #1						
61	1		*FRONT FENDER SIDE BRACKET RH (WCP)	Bent	40.00 F	*40.00 F
62	1		*FRONT CHASSIS BRACKET SIDE RH (WCP)	Bent	50.00 F	*50.00 F
63	1		*RADIATOR TOP SEAL (WCP)	Distorted	50.00 F	*50.00 F
64	1		*CONDENSER SUDE GARNISH (WCP)	Deformed	55.00 F	*55.00 F
65	1		*FRONT FENDER TOP COVER RH (WCP)	Deformed	40.00 F	*40.00 F
66	1		*FAN BELT (WCP)	Cut	50.00 F	*50.00 F
67	1		*AIR CLEANER BOX LOWER (WCP)	Cracked	320.00 F	*320.00 F
68	1		*RADIATOR SIDE SEAL (WCP)	Distorted	45.00 F	*45.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)					15,835.00	13,765.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					1,583.50	1,356.50
Total Parts (\$\$)					17,418.50	15,121.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT FENDER 1/4 GLASS GUM LH (NOT NECESSARY)	40.00	0.00
2	1	FRONT FENDER 1/4 GLASS GUM RH (NOT NECESSARY)	40.00	0.00
3	1	FRONT NUMBER PLATE (MISSING)	40.00	40.00
Sub Total (\$\$)			120.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,200.00	1,100.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	100.00	100.00
4	TO REMOVE/REFIT DASHBOARD	New	240.00	200.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	980.00	800.00
Gross Labour Cost (\$\$)			2,570.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >