S. REC.BY: Taylor - REF: CS/FG/2	FIGNMENT
	C112191 7011 Man
om: Date:	
stimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Nissan No to. c.c //98.
Workshop m/s	Colour Query A/C: Insured / Std / NI / NA
ſ	Sp.Reading /5 47% T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No. DMFG22005172	C/No: JNITHUE 12 20972254
Claims No. CDMFG22001587	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: (> 6 ° 0	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Vake of Veh:	Modi: Nil / S/Rim / STD A/Rim or
wake divoli	Tyre Size: F: (85/67 R15
(Policy Condition)	R: 1
(Policy Continuon) Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: \$48k	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6. mm
Est. Repairs: days Res.: Yes or No	D.O.A. 5/8/2022 D.O.I. 10/8/22
1 um Sum: % 3 Val.: Yes or No	Survey held at RFS
	Des. of Damages (Frt.) Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN /	OUT
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
15/11/22 Final fig \$17,391.50 confirmed b	by email (Red 2717, 13%)
,	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 9
; Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	Transportation:
	d Fee: : Site insp (\$)_s+Rssi
2 2	: Interview (\$) Photos
Represent: Merimen	:Tech. Invs (\$) Others
	:Weelend (\$
Lump Sum / LB.4: (* \$17,391.50)	
Lump Sum / L.B.R. (F \$17,391.50	TOTAL



61 Defu Lane 12, Singapore 539147 Tel: (65) 6747 9560, 6858 2126, 6858 4361

Fax: (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg * Website: www.carparts.com.sg

05/08/2022

UNKNOWN

29/04/2016

JN1TAAE12Z0972254

INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Policy No:

DMFG22005172

Vehicle Reg. No.:

SLC719C

Driver Age/Info:

TP Injury Involved?

Insured/Claimant:

YES

HWA SENG BUILDER PTE LTD

Make/Model:

NISSAN NOTE, 1.2 (A)

Vehicle Colour:

METALLIC GREY

Engine No:

HR12185104B

Odometer:

0 KM

Paint Type:

Total Loss?

Est. Duration of Repair

(day)

NO

15

Description of Accident/Loss

Present Location:

REMARK: RPICE MIGHT BE DIFFREENT DUT TO STOCK AVAILABILITY

Ref. No: Date of Loss:

Driveable?

Party At Fault:

Vehicle Reg. Date:

Chassis No:

Third Party Involved? YES

KAN FOOK SING MOTOR WORKSHOP (DEFU)

COST OF CLAIMS	Amount
Parts	16,703.50
Miscellaneous Items	120.00
Labour	1,370.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	19,393.50
- Excess (S\$)	600.00
(S\$)	18,793.50
+ GST 7.00% (S\$)	1,315.55
Nett Amount (S\$)	20,109.05

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Aug 2022)

Parts: 144 NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*STEERING AIR BAG	act 0.00	0.00	*1,500.00 F
2	1		*STEERING AIR BAG WIRE	act 0.00	0.00	*180.00 F
3	1		*DASHBOARD NO STOCK	de 0.00	0.00	-
4	1		*DASHBOARD AIR BAG	act-0.00	0.00	*2,200.00 F
5	1		*AIR BAG ECU NO STOCK	act 0.00	0.00	-
6	1		*AIR BAG SENSOR RH	act 0.00	0.00	*350.00 F
7	1		*AIR BAG SENSOR LH	aux 0.00	0.00	*350.00 F
8	1		*SEAT BELT RH	aut 0.00	0.00	*600.00 F
9	1		*SEAT BELT LH	0.00	0.00	*600.00 F
10	1		*FRONT WIPER CORNER GARNISH RH	0.00	0.00	*30.00 F
11	1		*FRONT WIPER CORNER GARNISH LH	0.00	0.00	*30.00 F
12	1		*FRONT BONNET	ht_0.00	0.00	*450.00 F
13	1		*FRONT BONNET LOCK	ht 0.00	0.00	*80.00 F
14	1		*FRONT BONNET HINGE RH	bt-0.00	0.00	*45.00 F
15	1		*FRONT BONNET HINGE LH	ht -0.00	0.00	*45.00 F
16	1		*FRONT BONNET STOPPER RH	M17 0.00	0.00	*30.00 F
17	1		*FRONT BONNET STOPPER LH	mis 0.00	0.00	*30.00 F
18	1		*FRONT SUPPORT PANEL	ht-0.00	0.00	*250.00 F
19	1		*FRONT SUPPORT GARNISH	0.00	0.00	*180.00 F
20	1		*FRONT LOWER MEMBER	0.00	0.00	*220.00 F
21	1		*FRONT FENDER RH	77 0.00	0.00	*320.00 F
22	1		*FRONT FENDER LH	hf 0.00	0.00	*320.00 F
23	1		*FRONT FENDER SHIELD RH	0.00	0.00	*95.00 F
24	20		*FRONT FENDER SHIELD CLIP	Ne 0.00	0.00	*50.00 F
25	1		*FRONT FENDER 1/4 GLASS MOULDING RH	0.00	0.00	*200.00 F
26	1		*FRONT FENDER 1/4 GLASS MOULDING LH	7 0.00	0.00	*200.00 F
27	1		*FRONT GRILLE	an 0.00	0.00	*210.00 F
28	1		*FRONT EMBLEM	ore 0.00	0.00	*50.00 F
29	1		*FRONT HEADLAMP RH	Cry 0.00	0.00	*1,200.00 F
30	1		*FRONT HEADLAMP LH	0.00	0.00	*1,200.00 F
31	1		*FRONT BUMPER	0.00	0.00	*350.00 F
32	1		*FRONT BUMPER SIDE RETAINER RH	dy 0.00	0.00	*30.00 F
33	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*30.00 F
34	1		*FRONT BUMPER FOAM NO STOCK	one 0.00	0.00	-
35	1		*FRONT BUMPER REINFORCEMENT	ht = 0.00	0.00	*250.00 F
36	1		*FRONT BUMPER REINFORCEMENT BRACKET RH	0.00	0.00	*220.00 F
37	1		*FRONT BUMPER REINFORCEMENT BRACKET LH	0.00	0.00	*220.00 F
38	1		*FRONT BUMPER TOW COVER NO STOCK	ant 0.00	0.00	-
39	10		*FRONT BUMPER CLIP	0.00	0.00	*25.00 F
40	1		*HORN	0.00	0.00	*80.00 F
41	1		*AIR CON CONDENSER	ht 0.00	0.00	*480.00 F
42	1		*AIR CON LIQUID PIPE	7 0.00	0.00	*120.00 F

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
43	1	*AIR CON SUCTION HOSE	0.00	0.00	*250.00 F
44	1	*AIR CON DISCHARGE HOSE	0.00	0.00	*250.00 F
45	1	*RADIATOR	0.00	0.00	*380.00 F
46	1	*RADIATOR HOSE TOP	0.00	0.00	*40.00 F
47	1	*RADIATOR HOSE LOWER	0.00	0.00	*40.00 F
48	1	*RAIDATOR TOP MOUNTING RH	0.00	0.00	*25.00 F
49	1	*RAIDATOR TOP MOUNTING LH	0.00	0.00	*25.00 F
50	1	*RADIATOR FAN ASSY	0.00	0.00	*320.00 F
51	1	*SPARE TANK	0.00	0.00	7 *70.00 F
52	1	*WASHER TANK	0.00	0.00	*125.00 F
53	1	*INTAKE MANIFOLD NO STOCK	0.00	0.00	-
54	1	*AIR CLEANER BOX NO STOCK	0.00	0.00	-
55	1	*AIR CLEANER HOSE	0.00	0.00	*150.00 F
56	1	*ALTERNATOR NO STOCK	0.00	0.00	7 -
57	1	*ENGINE MOUNTING RH	0.00	0.00	*195.00 F
58	1	*ENGINE MOUNTING LH	0.00	0.00	*85.00 F
59	1	*ENGINE MOUNTING RR	0.00	0.00	*80.00 F
60	1	*FRONT SIDE MIRROR RH	0.00	0.00	*330.00 F
F=Fra	anchise part.				1
			Sub Total (S\$)		15,185.00
		+ N	largin on L,N Items 10.00% (S\$)		1,518.50
			Total Parts (S\$)	16,703.50	

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
Mis	cella	neous Items		2
1	1	FRONT FENDER 1/4 GLASS GUM LH		40.00
2	1	FRONT FENDER 1/4 GLASS GUM RH		2 40.00
3	1	FRONT NUMBER PLATE		mis- 40.00
			Sub Total (S\$)	120.00

Estimates on Labour

No	Particulars	Lab.Type		Amount
Pair	ntwork Labour			
1	SPRAYPAINTING CHARGES	New	1100	1,200.00
Lab	our Items			
2	TO CHECK WIRING SYSTEM	New	30	50.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New		100.00
4	TO REMOVE/REFIT DASHBOARD	New	200	240.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	800	980.00
	Gross Labour	Cost (S\$)		2.570.00

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufihr 97495749 /62563561 expot Anthonise, Nevert Ex: 9600 10/8/12 e 1pm Resurrey before paint toutikh chhantoun oqdays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: