

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007593/UPA3Q2**Date:** 12/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210114809
Claimant Vehicle No :	SLC3707S	Insured Vehicle No :	SGX6171R
Date of Loss:	07/08/2022	Nature of Claim:	TP
		Claim No:	4446760510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3707S	Engine No:	G4FGGH612838
Make & Model:	KIA FORTE K3, 1.6 SX (A)	Chassis No:	KNAFZ411MG5600782
Reg. Date:	12/05/2016 (Man. Year: 2016)	Odometer:	78337 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,550.20	1,712.90	2,837.30	62.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,290.00	450.00	25.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,290.20	3,002.90	3,287.30	52.26
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	6,290.20	2,400.00	3,890.20	61.85
+ GST 7.00/7.00% (S\$)	440.31	168.00	272.31	61.85
Nett Amount (S\$)	6,730.51	2,568.00	4,162.51	61.85
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,810.00		

INSPECTION

Date of Assignment:	18/08/2022		
Date Inspected:	18/08/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	752.00 FL	*688.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Cracked	441.00 FL	*341.00 FL
4	1		*REAR BUMPER SPONGE	Not fitted	183.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER	N/S Bent	50.00 FL	*25.00 FL
6	2		*REAR BUMPER BRACKET	Twisted (1 PCS ONLY)	340.00 FL	*170.00 FL
7	2		*REAR BUMPER TOP BRACKET	Twisted (1 PCS ONLY)	130.00 FL	*35.00 FL
8	1		*REAR BUMPER LOWER COVER	Distorted	282.00 FL	*282.00 FL
9	1		*REAR END PANEL	Repair	692.00 FL	*- FL
10	1		*REAR END PANEL INNER TRIM	Not Necessary	225.00 FL	*- FL
11	1		*BOOTLID	Repair	1,298.00 FL	*- FL
12	1		*BOOTLID CERATO EMBLEM	Necessary	65.00 FL	*65.00 FL
13	1		*BOOTLID K3 EMBLEM	Necessary	25.00 FL	*25.00 FL
14	1		*BOOTLID CENTRE EMBLME BADGE	Not Necessary	85.00 FL	*- FL
15	1		*BOOTLID C&C BADGE	Not Necessary	35.00 FS	*- FS
16	1		*SET REAR PARKING SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,013.00	1,881.00
- List Item Discount on L Items 10.00/10.00% (S\$)	462.80	168.10
Total Parts (S\$)	4,550.20	1,712.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	20.00
4	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	80.00	0.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	650.00	600.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	600.00
Gross Labour Cost (\$\$)			1,740.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >