CL APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Sulaiman Bin Daud

C/o: H L Cycle Pte Ltd No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

Accident Date

: 24 October 2021

Inspection Date

: 26 October 2021

Repairer Name : H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

PARTICULARS OF VEHICLE

Registration No

: FBS 8346 B

Make / Model

Yamaha Xmax

Chassis No

: MH3SG3910LK034559

Engine No

: G3H4E0041308

Year / Capacity:

Date

Our ref

Type of Survey: Third Party

2021 / 250 cc

: 11 November 2021

: HLC/10/2102/TP

Colour

Black

Mileage

6833

CONDITION OF TYRES

Make

Size

Thread Balance

Rim

Front

Maxxis

120/70-15

5 mm

Sport

Rear

Maxxis

140/70-14

5 mm

Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and n/s portion. (Details refer to the photographs attached)

Enclosed number of photographs:

<u>116</u>

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$6,000.00 on a contractual basis.

Under normal circumstances, the repair period would be about 14 (Fourteen) working days.

CL APPRAISER PTE LTD

Vehicle Registration No.: FBS 8346 B Our Ref No.: HLC/10/2102/TP Repairer's Qty Revised Description **Conditions Estimate** Amount SPARE PARTS - LIST ITEMS 1 Front sport rim \checkmark Damage \$ 550.00 \$ 550.00 🖊 1 Front brake disc SVC \$ Intact 180.00 1 Headlamp \ Damage \$ 550.00 \$ 550.00 🗸 1 Handle-bar 🗸 \$ Damage \$ 135.00 135.00 🗸 1 Handle-bar balancer Damage \$ 80.00 \$ 80.00 🗸 1 Hand grip (1 set) X SVC Damage \$ 60.00 \$ 60.00 1 Clutch lever \ Damage \$ 52.00 \$ 52.00 Front n/s signal X SVC Damage \$ 75.00 \$ 75.00 1 Exhaust assy \ Damage \$ 880.00 \$ 880.00 🗸 Rear n/s footrest \checkmark 1 Damage \$ 65.00 \$ 65.00 🗸 Engine cover X SVC 1 Damage \$ 350.00 \$ 350.00 1 Air filter box cover \/ Damage \$ 150.00 \$ 150.00 🗸 1 Main stand \ Damage \$ 145.00 \$ 145.00 1 Side stand \checkmark Damage \$ 95.00 \$ 95.00 🗸 1 Rear fender \checkmark \$ Damage 155.00 \$ 155.00 Rear wheel rim X SVC 1 \$ Damage 550.00 \$ 550.00 Rear rim bracket X SVC Damage \$ 322.00 \$ 322.00 1 Rear rim bracket disc X SVC Damage \$ 158.00 \$ 158.00 Fairing cover (1 set) Damage \$ 1,350.00 \$ 1,350.001050 5,902.00 \$ 5,722.00 Less 10% \$ 590.20 \$ 572.20 **Total Cost - List Items** 5,311.80 5,149.80 3516.3 SPECIAL NETT ITEMS 1 Side mirror (1 set) \checkmark Damage \$ 200.00 \$ 200.00 100 Number plate (1 set) ✓ 1 Damage \$ 28.00 \$ 28.00 15 1 "X MAX" emblem 🗸 Necessry \$ 60.00 \$ 60.00 30 1 Exhaust pipe carbon cover \checkmark Damage \$ 320.00 \$ 320.00 150 1 Rear shock absorber (1 set) \checkmark Damage \$ 880.00 \$ 880.00 200 **Total Cost - Special Nett items** \$ 1,488.00 1,488.00495

Total	onet	۸£	mauta
I VLAI	CUST	UI.	บนเธ

_\$	6,799.80	\$ 6,637.80

CL APPRAISER PTE LTD

Vehicle Registration No.: FBS 8346 B

Our Ref No.:

HLC/10/2102/TP

S/No	2 ostription	Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	6,799.80	\$	6,637.80
	<u>LABOUR</u>				
1	To provide towing service.	\$	50.00	\$	50.00 🗸
2	To check electrical system, wire harness and focus headlamp.	\$	80.00	\$	50.00
3	To provide labour charges, workmanship to dismantle above damaged parts; re-align body structure and damaged consistent to the accident.	\$	480.00	\$	400.00 30
4	To check, repair and straighten body frame to the original position.	\$	350.00	\$	350.00 🔀
	GRAND TOTAL	\$	7,759.80	\$	7,487.80

4361.3

-20%: 3500

3 Days



Vehicle Registration No.: FBS 8346 B

Our Ref No.:

HLC/10/2102/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 6,000.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser