



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 8346B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT SPORT RIM	DAMAGED	550.00	550.00
1	FRONT BRAKE DISC	SERVICEABLE	180.00	-
1	HEADLAMP	DAMAGED	550.00	550.00
1	HANDLE-BAR	DAMAGED	135.00	135.00
1	HANDLE-BAR BALANCER	DAMAGED	80.00	80.00
1	SET HAND GRIP	SERVICEABLE	60.00	-
1	CLUTCH LEVER	DAMAGED	52.00	52.00
1	FRONT N/S SIGNAL	SERVICEABLE	75.00	-
1	EXHAUST ASSY	DAMAGED	880.00	880.00
1	REAR N/S FOOTREST	DAMAGED	65.00	65.00
1	ENGINE COVER	SERVICEABLE	350.00	-
1	AIR FILTER BOX COVER	DAMAGED	150.00	150.00
1	MAIN STAND	DAMAGED	145.00	145.00
1	SIDE STAND	DAMAGED	95.00	95.00
1	REAR FENDER	DAMAGED	155.00	155.00
1	REAR WHEEL RIM	SERVICEABLE	550.00	-
1	REAR RIM BRACKET	SERVICEABLE	322.00	-
1	REAR RIM BRACKET DISC	SERVICEABLE	158.00	-
1	SET FAIRING COVER	DAMAGED	1,350.00	1,050.00
	LESS 10% DISCOUNT		-590.20	-390.70
			5,311.80	3,516.30
<u>SPECIAL NETT ITEMS</u>				
1	SET SIDE MIRROR (SN)	DAMAGED	200.00	100.00
1	SET NUMBER PLATE (SN)	DAMAGED	28.00	15.00
1	"X MAX" EMBLEM (SN)	NECESSARY	60.00	30.00
1	EXHAUST PIPE CARBON COVER (SN)	DAMAGED	320.00	150.00
1	SET REAR SHOCK ABSORBER (SN)	DAMAGED	880.00	200.00
			1,488.00	495.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE.		50.00	50.00

Report Ref No. CS3/ASM21010944/Gqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	300.00
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	NOT NECESSARY	350.00	-
			960.00	350.00
GRAND TOTAL			7,759.80	4,361.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS3/ASM21010944/Gqy3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.