

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007598/AVY3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00223922100		
Claimant Vehicle No :	SMW9498M	Insured Vehicle No :	SJQ2573S		
Date of Loss:	08/08/2022	Nature of Claim:	TP	Claim No:	SNM22D205525/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW9498M	Engine No:	2ZR2F92148
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDZS3EU50J052944
Reg. Date:	18/12/2020 (Man. Year: 2019)	Odometer:	128805 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,824.87	5,911.22	3,913.65	39.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,330.00	1,810.00	57.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,964.87	7,241.22	5,723.65	44.15
Approved Total (Overridden) (\$\$)		5,800.00		
Nett Amount (\$\$)	12,964.87	5,800.00	7,164.87	55.26

INSPECTION

Date of Assignment:	10/08/2022		
Date Inspected:	16/08/2022	Inspected At:	Unimotor Co (HQ) NO 1 KAKI BUKIT AVE 6 #01-94 Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2023)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW9498M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H FENDER ASSY	Dented	1,060.70 FL	*521.00 FL
2	1		*FRONT L/H FENDER TOP GLASS	Cut	295.80 FL	*295.80 FL
3	1		*FRONT L/H FENDER INNER SHIELD	Not Necessary	236.70 FL	*- FL
4	8		*FRONT L/H FENDER INNER SHIELD CLIPS	Not Necessary	44.00 FL	*- FL
5	1		*FRONT L/H FENDER HYBRID EMBLEM	Necessary	67.70 FL	*67.70 FL
6	1		*FRONT L/H HEADLAMP ASSY	Cut	2,731.20 FL	*2,526.00 FL
7	1		*FRONT BUMPER FACE	Deformed	602.60 FL	*602.60 FL
8	1		*FRONT BUMPER DAYTIME LAMP ASSY	Cracked	632.20 FL	*632.20 FL
9	1		*FRONT BUMPER DAYTIME LAMP COVER	Not Necessary	87.60 FL	*- FL
10	1		*FRONT BUMPER L/H SIDE INNER BRACKET	Not Necessary	72.80 FL	*- FL
11	1		*FRONT L/H BUMPER SIDE RETAINER	Damaged	90.80 FL	*42.00 FL
12	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
13	1		*FRONT L/H SHOCK ABSORBER UNIT	Not Necessary	475.80 FL	*- FL
14	1		*FRONT LR/H SHOCK ABSORBER TOP MOUNTING	Not Necessary	254.90 FL	*- FL
15	1		*FRONT L/H LOWER ARM	Bent	852.20 FL	*581.00 FL
16	1		*FRONT L/H WHEEL HUB ASSY & BEARING	Damaged	722.10 FL	*453.00 FL
17	1		*FRONT L/H KNUCKLE ASSY	Damaged	755.10 FL	*687.00 FL
18	1		*FRONT L/H DOOR ASSY	Not Necessary	1,435.20 FL	*- FL
19	1		*FRONT L/H DOOR TOP BLACK STICKER	Not Necessary	96.20 FL	*- FL
20	1		*FRONT L/H DOOR WIND MIRROR	Damaged	1,399.60 FL	*1,294.00 FL
21	1		*FRONT L/H DOOR WIND MIRROR COVER	Repair	142.30 FL	*- FL
22	1		*FRONT L/H SPORT RIM	Not Necessary	450.00 FS	*- FS
23	1		*FRONT L/H RIM COVER GARNISH	Cut	112.00 FS	*112.00 FS
24	1		*FRONT L/H TYRE	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,852.50	7,844.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,027.63	1,933.08
Total Parts (\$\$)	9,824.87	5,911.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/RENEW FRONT FENDER TOP GLASS	New	140.00	50.00
2	TO SPRAY UNDERCOATING IN REPAIR	New	180.00	50.00
3	TO SEND VEHICLE FOR FRONT COMPUTER ALIGNMENT	New	120.00	80.00
4	TO DISM/REWIRE DAMAGED PORTION	New	200.00	30.00
5	TO DISM/RENEW FRONT UNDERCARRIAGE IN REPAIR	New	500.00	220.00
6	TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION AND RENEW PARTS	New	1,000.00	500.00
7	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	400.00
Gross Labour Cost (S\$)			3,140.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >