

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007604/KYA3Q2
Date: 14/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220069408
Claimant Vehicle No :	SMZ3573C	Insured Vehicle No :	GBL9036B
Date of Loss:	06/08/2022	Nature of Claim:	TP
		Claim No:	7634550355SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ3573C		
Make & Model:	MERCEDES-BENZ GLC300 SPORT, 2.0 4MATIC M-HYBRID (A)	Engine No:	26492030209221
Reg. Date:	06/04/2020 (Man. Year: 2019)	Chassis No:	WDC2533842F730682
Colour:	Metallic Grey	Odometer:	40270 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,589.00	13,224.10	13,364.90	50.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,830.00	1,590.00	46.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	30,009.00	15,054.10	14,954.90	49.83
+ GST 7.00/7.00% (S\$)	2,100.63	1,053.79	1,046.84	49.83
Nett Amount (S\$)	32,109.63	16,107.89	16,001.74	49.83
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,709.89		

INSPECTION

Date of Assignment:	15/08/2022		
Date Inspected:	15/08/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Serviceable	1,875.00 FL	*- FL
2	1		*FRONT WINDSCREEN RAIN SENSOR	Serviceable	475.00 FL	*- FL
3	1		*FRONT WIPER ARM LH	Contaminated	180.00 FL	*180.00 FL
4	1		*FRONT WIPER ARM RH	Contaminated	180.00 FL	*180.00 FL
5	1		*FRONT BONNET	Repair	3,540.00 FL	*- FL
6	1		*FRONT BONNET EMBLEM	Necessary	80.00 FL	*80.00 FL
7	1		*FRONT HEADLAMP LH	Contaminated	6,390.00 FL	*4,881.00 FL
8	1		*FRONT GRILLE BASE	Contaminated	190.00 FL	*190.00 FL
9	1		*FRONT GRILLE LOGO EMBLEM	Necessary	400.00 FL	*400.00 FL
10	1		*FRONT GRILLE OUTER GARNISH	Contaminated	270.00 FL	*270.00 FL
11	1		*FRONT GRILLE CHROME MOULDING LH	Contaminated	240.00 FL	*240.00 FL
12	1		*FRONT GRILLE TOP CHROME MOULDING LH	Contaminated	440.00 FL	*440.00 FL
13	1		*FRONT GRILLE BOTTOM CHROME MOULDING LH	Contaminated	440.00 FL	*440.00 FL
14	1		*FRONT BUMPER	Repair	3,400.00 FL	*- FL
15	1		*FRONT BUMPER LOWER GRILLE	Contaminated	400.00 FL	*400.00 FL
16	1		*FRONT BUMPER LOWER GRILLE LH	Contaminated	150.00 FL	*150.00 FL
17	1		*FRONT BUMPER PARKING SENSOR (2PCS)	Shorted(1Pc only)	300.00 FL	*150.00 FL
18	1		*FRONT BUMPER LOWER CHROME MOULDING LH	Contaminated	150.00 FL	*150.00 FL
19	1		*FRONT BUMPER LOWER CHROME MOULDING CENTER	Contaminated	600.00 FL	*520.00 FL
20	1		*FRONT BUMPER SIDE GARNISH COVER LH	Contaminated	140.00 FL	*140.00 FL
21	1		*FRONT FENDER LH	Repair	1,300.00 FL	*- FL
22	1		*FRONT FENDER WHEEL ARCH COVER LH	Contaminated	260.00 FL	*260.00 FL
23	1		*FRONT DOOR OUTER HANDLE LH	Contaminated	640.00 FL	*560.00 FL
24	1		*FRONT DOOR OUTER MOULDING LH	Serviceable	200.00 FL	*- FL
25	1		*A-PILLAR MOULDING LH	Contaminated	300.00 FL	*300.00 FL
26	1		*A-PILLAR CHROME MOULDING LH	Contaminated	260.00 FL	*260.00 FL
27	1		*FRONT SIDE MIRROR ASSY LH	Contaminated	2,250.00 FL	*2,180.00 FL
28	1		*REAR DOOR OUTER HANDLE LH	Contaminated	640.00 FL	*508.00 FL
29	1		*REAR DOOR OUTER OULDING LH	Serviceable	200.00 FL	*- FL
30	1		*REAR FENDER WHEEL ARCH COVER LH	Contaminated	320.00 FL	*320.00 FL
31	1		*A-PILLAR LH (NPA)	Repair	0.00 FL	*- FL
32	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
33	1		*REAR DOOR LH (NPA)	Repair	0.00 FL	*- FL
34	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
35	1		*FRONT WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
36	1		*FRONT IU STICKER	Not Necessary	20.00 FS	*- FS
37	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
38	1		*FRONT FENDER WHEEL ARCH LH CLIPS	Necessary	40.00 FS	*40.00 FS
39	1		*SIDE STEP LH	Serviceable	1,400.00 FS	*- FS
40	1		*REAR FENDER WHEEL ARCH CLIPS LH	Necessary	40.00 FS	*40.00 FS
41	1		*FRONT SIDE MIRROR CAMERA LH	Glue	1,500.00 FL	*1,350.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,360.00	14,679.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,771.00	1,454.90
Total Parts (\$)	26,589.00	13,224.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST AFFECTED AREAS & ETC	New	1,500.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH & ETC	New	1,500.00	1,400.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC	New	150.00	0.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	30.00
Gross Labour Cost (S\$)			3,420.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >