

ASS. REC. BY:

REF:

AIG / 220076041kg

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ *Optima*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_


(Client's Record)

Make of Veh: \_\_\_\_\_

*Ipri*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *8256k*

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *06* days Res.: Yes or No

Lum Sum: *1.3.1* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *Sm 8 3573C* Yr Regn: *04 20*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Mer G6C300* *1991*

Colour: *M. Gray* A/C: Insured / Std / NI / NA

Sp. Reading: *40270* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *WDC 2533842F 730682*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / *STD A/Rim* or

Tyre Size: F: \_\_\_\_\_ R: \_\_\_\_\_

*255/50R19*

BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. *3* mm

L/Bal. *3* mm

D.O.A. *6/8/22*

Rear

R/Bal. *4* mm

L/Bal. *4* mm

D.O.I. *15/8/2022*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*The vehicle found damaged at the front portion at the time of inspection. The cause of damage due to chemical agent. (Super glue)*

*The U/C / Chassis frame / Body Structure affected due to collision.*

Date / Time Action / Instruction

*25/11 814840.10*

*5/12 815054.10 Condr*

Date/Time, File Pass to?

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

\$ - RS. SI

Fees

Others

TOTAL

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)



Date: 13/08/2022  
 Vehicle No: SMZ3573C  
 Model: MERCEDES BENZ GLC300 M-HYBRID COUPE  
 Chassis: WDC2533842F730682-2019  
 Reg.Year: 2020

Third Party Insurer: AIG  
 Third Party Veh No: GBL9036B  
 Date of Accident: 06/08/2022  
 Estimator: TING AN  
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN SEALANT	1		<i>nn</i> \$100.00
2	FRONT IU STICKER	1		<i>nn</i> \$20.00
3	FRONT BUMPER CLIPS	1		<i>nn</i> \$50.00
4	FRONT FENDER WHEEL ARCH LH CLIPS	1		<i>nn</i> \$40.00
5	SIDE STEP LH	1		<i>nn</i> \$1,400.00
6	REAR FENDER WHEEL ARCH CLIPS LH	1		<i>nn</i> \$40.00
S/N TOTAL				\$1,650.00

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST AFFECTED AREAS & ETC. \$1,500.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH & ETC. \$1,500.00 *1400*

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC. *nn* \$150.00 *7*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. *nn* \$150.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$120.00 *30*

**LABOUR TOTAL** \$3,420.00

TING AN

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**TOTAL** \$28,245.00

**Head office**

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 11/10/2022 Third Party Insurer: AIG  
 Vehicle No: SMZ3573C Third Party Veh No: GBL9036B  
 Model: MERCEDES BENZ GLC300 M-HYBRID C Date of Accident: 06/08/2022  
 Chassis: WDC2533842F730682-2019  
 Reg.Year: 2020

### SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR CAMERA LH <i>1350</i>	1	<i>Labour</i>	\$1,500.00
SUB TOTAL				\$1,500.00
LESS 10%				-\$150.00
PARTS TOTAL				\$1,350.00

TING AN	TOTAL	\$1,350.00
---------	-------	------------

*Finalize:*  
 Parts : \$13563  
 Supp : \$1350  
 Nett : \$130  
 Labour : \$1950  
PIP : \$16993

**Head office**

6 Kung Chang Road Singapore 160143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6451 1903

**Branch (Motor Insurance Claims)**

BR 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

