

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22007605/AGNCE2  
**Date:** 13/01/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960246
<b>Claimant Vehicle No :</b>	GBL3185T	<b>Insured Vehicle No :</b>	SLK3541K
Date of Loss:	08/08/2022	Nature of Claim:	TP
		Claim No:	281438

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBL3185T</b>	Engine No:	QR20018835R
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)	Chassis No:	JN1MA2E26Z0000051
Reg. Date:	28/05/2021 (Man. Year: 2021)	Odometer:	19983 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,593.27	6,747.16	3,846.11	36.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	2,260.00	2,170.00	48.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,023.27</b>	<b>9,007.16</b>	<b>6,016.11</b>	<b>40.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,023.27</b>	<b>7,200.00</b>	<b>7,823.27</b>	<b>52.07</b>

INSPECTION

Date of Assignment:	11/08/2022	
Date Inspected:	10/08/2022 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	8.0 days	

**Adjuster:** XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Jan 2023)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL3185T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	709.80 FL	*676.00 FL
2	1		*FRONT BUMPER LH SIDE HOLDER	Damaged	224.90 FL	*104.00 FL
3	1		*FRONT BUMPER LH SIDE LOWER GARNISH	Deformed	133.40 FL	*133.40 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	963.90 FL	*- FL
5	1		*FRONT GRILLE	Cracked	741.40 FL	*579.00 FL
6	1		*FRONT LOWER GRILLE	Not Necessary	1,168.40 FL	*- FL
7	1		*FRONT LH HEADLAMP	Smashed	720.00 FL	*720.00 FL
8	1		*FRONT LH CORNER PANEL	Dented	664.50 FL	*468.00 FL
9	1		*FRONT LH STEP PANEL	Repair	175.30 FL	*- FL
10	1		*FRONT LH STEP PANEL TOP GARNISH	Deformed	97.50 FL	*97.50 FL
11	1		*FRONT LH DOOR	Distorted	1,494.10 FL	*1,358.00 FL
12	1		*FRONT LH DOOR TOP HINGE	Not Necessary	80.40 FL	*- FL
13	1		*FRONT LH DOOR LOWER HINGE	Bent	80.40 FL	*80.40 FL
14	1		*FRONT LH DOOR STOPPER	Not Necessary	21.30 FL	*- FL
15	1		*FRONT LH DOOR LOWER RUBBER	Not Necessary	215.60 FL	*- FL
16	1		*FRONT LH DOOR WEATHERSTRIP	Cut	152.80 FL	*152.80 FL
17	1		*FRONT LH DOOR INNER BOARD	Cracked	626.40 FL	*626.40 FL
18	1		*FRONT LH DOOR INNER LOCK	Not Necessary	214.10 FL	*- FL
19	1		*FRONT LH DOOR SIDE BLACK MOULDING	Not Necessary	50.00 FL	*- FL
20	1		*FRONT LH DOOR SUN VISOR	Necessary	50.00 FL	*50.00 FL
21	1		*FRONT LH DOOR PILLAR }	Dented	1,437.20 FL	*1,256.00 FL
22	1		*FRONT LH ARCH PANEL }		0.00 FL	*- FL
23	1		*FRONT LH WHEEL CAP	Cut	200.60 FN	*100.00 F
24	1		*FRONT LH OIL COOLER	Dented	869.90 FL	*869.90 FL
25	1		*FRONT LH OIL COOLER COVER	Cracked	228.40 FL	*131.00 FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*SET FRONT LH STEP PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
28	1		*FRONT LH DOOR COMPANY STICKER	Necessary	25.00 FS	*25.00 FS
29	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>11,725.30</b>	<b>7,477.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,111.97	730.24
<b>- Nett Item Discount on N Items 10.00/0.00% (\$)</b>	20.06	0.00
<b>Total Parts (\$)</b>	<b>10,593.27</b>	<b>6,747.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	TO SUPPLY FRONT WINDSCREEN SEALANT	New	50.00	0.00
3	REMOVE & REINSTALL FRONT WINDSCREEN	New	200.00	0.00
4	REMOVE & REINSTALL DESKBOARD	New	380.00	0.00
5	REMOVE & REINSTALL DOOR FITTINGS	New	150.00	80.00
6	REMOVE & REINSTALL AIR CON FILL IN GAS	New	150.00	0.00
7	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	1,000.00
8	RESPRAY PAINTING	New	1,500.00	1,000.00
9	TUFF KOTE	New	100.00	100.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,430.00</b>
				<b>2,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >