

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TP MS19. Xiao Chu.

Name : WEI JIE ELECTRICAL MOTOR SERVICES

Make/Model : NISSAN NV350

Vehicle No : GBL 3185 T

Accident date : 08.08.2022

JN1MA2E26Z0000051

No	DESCRIPTION	Qty	Amount (S\$)
List Items			
1	Front bumper <i>Distorted.</i>	1	\$ 709.80
2	Front bumper LH side holder <i>Dented</i>	1	\$ 224.90
3	Front bumper LH side lower garnish <i>Behind</i>	1	\$ 133.40
4	Front bumper reinforcement <i>New</i>	1	\$ 963.90
5	Front grille <i>Cracked</i>	1	\$ 741.40
6	Front lower grille <i>New</i>	1	\$ 1,168.40
7	Front LH headlamp <i>Smashed.</i>	1	\$ 720.00
8	Front LH corner panel <i>Dented.</i>	1	\$ 664.50
9	Front LH step panel <i>Repair</i>	1	\$ 175.30
10	Front LH step panel top garnish <i>Behind</i>	1	\$ 97.50
11	Front LH door <i>Distorted</i>	1	\$ 1,494.10
12	Front LH door top hinge <i>New</i>	1	\$ 80.40
13	Front LH door lower hinge <i>Best</i>	1	\$ 80.40
14	Front LH door stopper <i>New</i>	1	\$ 21.30
15	Front LH door lower rubber <i>New</i>	1	\$ 215.60
16	Front LH door weather strip <i>at</i>	1	\$ 152.80
17	Front LH door inner board <i>Cracked.</i>	1	\$ 626.40
18	Front LH door inner lock <i>New</i>	1	\$ 214.10
19	Front LH door side black moulding <i>New</i>	1	\$ 50.00
20	Front LH door sun <i>visor New</i>	1	\$ 50.00
21	Front LH door pillar <i>Dented.</i>	1	\$ 1,437.20
22	Front LH arch panel <i>New</i>	1	\$
23	Front LH wheel cap <i>at.</i>	1	\$ 200.60
24	Front LH oil cooler <i>Dented</i>	1	\$ 869.90
25	Front LH oil cooler cover <i>cracked.</i>	1	\$ 228.40
			\$ 11,320.30
		Less 10% Disc	\$ 1,132.03
		Total	\$ 10,188.27

7302.40

6572.16

S.N. 100

626
104.
579.
468.
1358
1256.
180/sw
131.

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : WEI JIE ELECTRICAL MOTOR SERVICES

Make/Model : NISSAN NV350

Vehicle No : GBL 3185 T

Accident date : 08.08.2022

No	DESCRIPTION	Qty	Amount (S\$)
Special Nett Items			
1	Front bumper clips (1 set) <i>new</i>	1	\$ 50.00 <i>30</i>
2	Front LH step panel top garnish clips (1 set) <i>new</i>	1	\$ 50.00 <i>20</i>
3	Front LH door company sticker <i>new</i>	1	\$ 25.00 <i>✓</i>
4	Front LH tyre <i>ATC new</i>	1	\$ 280.00 <i>X</i>
	<i>75</i>	Total	\$ 405.00

Labour Cost			
1	To check wheel alignment		\$ 100.00 <i>80</i>
2	To supply front windscreen sealant		\$ 50.00 <i>+</i>
3	Remove & reinstall front windscreen		\$ 200.00 <i>+</i>
4	Remove & reinstall deskboard		\$ 380.00 <i>+</i>
5	Remove & reinstall door <i>glass fittings</i>		\$ 150.00 <i>80</i>
6	Remove & reinstall air con fill in gas		\$ 150.00 <i>X</i>
7	Remove, replace & repair consistent to the accident		\$ 1,800.00 <i>1000</i>
8	Respray painting		\$ 1,500.00 <i>1000</i>
9	Tuff kote		\$ 100.00 <i>✓</i>
	<i>2260</i>	Total	\$ 4,430.00
		Grand Total	\$ 15,023.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 9007.16

4/s: 7.2K

08 Days

7.2K