

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007606/EVY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009252101		
Claimant Vehicle No :	SHB3139J	Insured Vehicle No :	SLR4663Z		
Date of Loss:	09/08/2022	Nature of Claim:	TP	Claim No:	SNM22D205568/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3139J		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU660932
Reg. Date:	14/07/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU092312
Colour:	Yellow	Odometer:	807333 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,391.82	6,469.02	1,922.80	22.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	2,070.00	2,130.00	50.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,591.82	8,539.02	4,052.80	32.19
Approved Total (Overridden) (\$\$)		6,850.00		
(\$\$)	12,591.82	6,850.00	5,741.82	45.60
+ GST 7.00/7.00% (\$\$)	881.43	479.50	401.93	45.60
Nett Amount (\$\$)	13,473.25	7,329.50	6,143.75	45.60

INSPECTION

Date of Assignment:	10/08/2022		
Date Inspected:	11/08/2022	Inspected At:	Ding Automotive Pte Ltd (SIN MING) BLK 10 #01-20 SIN MING, IND EST SEC C Singapore 575645
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2022)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB3139J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR PANEL	Dented	2,256.00 FL	*2,256.00 FL
2	1		*FRONT RH SIDE MIRROR	Broken	586.30 FL	*586.30 FL
3	1		*FRONT RH OUTER DOOR GLASS MOULDING	Bent	107.85 FL	*107.85 FL
4	1		*FRONT RH DOOR GLASS	Cut	705.68 FL	*228.20 FL
5	1		*FRONT RH DOOR POWER WINDOW REGULATOR	Not Necessary	350.10 FL	*- FL
6	1		*FRONT RH OUTER DOOR HANDLE	Repair	68.90 FL	*- FL
7	1		*FRONT RH OUTER DOOR HANDLE COVER	Repair	10.75 FL	*- FL
8	1		*REAR RH DOOR PANEL	Dented	2,201.00 FL	*2,201.00 FL
9	1		*REAR RH OUTER DOOR HANDLE	Not Necessary	68.90 FL	*- FL
10	1		*REAR RH OUTER DOOR HANDLE COVER	Not Necessary	10.85 FL	*- FL
11	1		*REAR RH QUARTER PANEL	Dented	2,171.50 FL	*2,171.50 FL
12	1		*REAR RH DOOR GLASS	Not Necessary	705.68 FL	*- FL
13	1		*FRONT RH DOOR FRAME UPPER CHROME MOULDING	Not Necessary	39.80 FL	*- FL
14	1		*FRONT RH DOOR FRAME REAR BLACK MOULDING	Cut	71.50 FL	*71.50 FL
15	1		*FRONT RH DELTA GARNISH	Not Necessary	102.30 FL	*- FL
16	1		*FRONT DOOR COMFORT DELGRO STICKER	Necessary	120.00 FS	*80.00 FS
17	1		*SET FRONT AND REAR DOOR MOULDING CLIP	Not Necessary	55.00 FS	*- FS
18	1		*REAR DOOR GOOGLE PLAY STORE STICKER	Necessary	100.00 FS	*40.00 FS
19	1		*REAR DOOR COMFORT DELGRO STICKER	Necessary	100.00 FS	*80.00 FS
20	2		*REAR WINDSCREENP PRIMER	Necessary	100.00 FS	*30.00 FS
21	1		*REAR WINDSCREENP SEALANT (3 PCS)	Necessary	150.00 FS	*40.00 FS
22	2		*REAR QUARTER PANEL SEALANT	Necessary	120.00 FS	*20.00 FS
23	1		*REAR WINDSCREEN MOULDING	Necessary	101.42 FL	*101.42 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,303.53	8,013.77
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,911.71	1,544.75
Total Parts (\$\$)	8,391.82	6,469.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	1,600.00	1,000.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	200.00	50.00
4	TO REFIT REAR REVERSE SENSOR	New	100.00	0.00
5	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	200.00	30.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND QUARTER GLASS TO ENABLE BODYWORK REPAIR	New	260.00	180.00
7	TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
8	TO RESPRAY FRONT DOOR PANEL	New	250.00	200.00
9	TO RESPRAY FRONT SIDE MIRROR	New	250.00	50.00
10	TO RESPRAY REAR RH DOOR PANEL	New	250.00	200.00
11	TO RESPRAY REAR RH QUARTER PANEL	New	250.00	200.00
12	TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE AND COVER	New	250.00	30.00
13	TO RESPRAY FRONT FENDER PANEL	New	250.00	0.00
Gross Labour Cost (\$)			4,200.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >