

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SLR 4663Z

Policy No. DMHCSNA00009252101

Claims No. SNM22D205568/C02/TANCHC


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 3139J Yr Regn: 14/7/16

Type: M. Car / M. Cycle / Bus / Van / Lorry (Tax) / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading 807333 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KIMHL 841 UM GV 092347

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 185/60R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 9/8/22 D.O.I. 11/8/22

Survey held at Ding Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/9/22 Steve informed LS \$6850 (Red 5742.08, 45%)

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 6/9/22-typist

Report Format: Merimen

Lump Sum H.R. (\$) \$6850

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$ \_\_\_\_\_

Photos

Others

TOTAL

TO :

FAX NO:

**ESTIMATE REPORT** 1ST Quotation

10/08/2022 11:36

JOB-NO: 50114376

**OWNER'S PARTICULARS**

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE  
SINGAPORE 575717 0

64739522

**VEHICLE DETAILS**

LICENSE NO: SHB3139J

TRANS: AUTO

CHASSIS: KMHLB41UMGU092312

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU660932

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

**CLAIM DETAILS**

| DESCRIPTION                                                                                    | QTY  | QUOTED COSTS | DISCOUNT   | DISC PRICE | IND    | SUR.DISP | REV PRICE |
|------------------------------------------------------------------------------------------------|------|--------------|------------|------------|--------|----------|-----------|
| <b>LABOUR</b>                                                                                  |      |              |            |            |        |          |           |
| 1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA                                       | 1.00 | 1,600.00     | 0.00       | 1,600.00   | 1991   | Y        | _____     |
| 2 TO RUST PROOFING OF THE AFFECTED AREA                                                        | 1.00 | 170.00       | 0.00       | 170.00     | 30     | Y        | _____     |
| 3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR                         | 1.00 | 200.00       | 0.00       | 200.00     | 50     | Y        | _____     |
| 4 TO REFIT REAR REVERSE SENSOR                                                                 | 1.00 | 100.00       | 0.00       | 100.00     | 30 X   | Y        | _____     |
| 5 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE                         | 1.00 | 200.00       | 0.00       | 200.00     | 30     | Y        | _____     |
| 6 TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND QUARTER GLASS TO ENABLE BODYWORK REPAIR        | 1.00 | 260.00       | 0.00       | 260.00     | 12 150 | Y        | _____     |
| 7 TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST | 1.00 | 170.00       | 0.00       | 170.00     | 80     | Y        | _____     |
| 8 TO RESPRAY FRONT DOOR PANEL                                                                  | 1.00 | 250.00       | 0.00       | 250.00     | 200    | Y        | _____     |
| 9 TO RESPRAY <del>SIDE SKIRT RH</del> Port side mirror                                         | 1.00 | 250.00       | 0.00       | 250.00     | 30     | Y        | _____     |
| 10 TO RESPRAY REAR RH DOOR PANEL                                                               | 1.00 | 250.00       | 0.00       | 250.00     | 200    | Y        | _____     |
| 11 TO RESPRAY REAR RH QUARTER PANEL                                                            | 1.00 | 250.00       | 0.00       | 250.00     | 200    | Y        | _____     |
| 12 TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE AND COVER                                       | 1.00 | 250.00       | 0.00       | 250.00     | 30     | Y        | _____     |
| 13 TO RESPRAY FRONT FENDER PANEL                                                               | 1.00 | 250.00       | 0.00       | 250.00     | X      | Y        | _____     |
| TOTAL:                                                                                         |      | 4,200.00     | 0.00       | 4,200.00   |        |          | _____     |
| <b>MATERIALS</b>                                                                               |      |              |            |            |        |          |           |
| 1 FRONT RH DOOR PANEL / 00                                                                     | 1.00 | 2,256.00     | 451.20     | 1,804.80   | L      | Y        | _____     |
| 2 FRONT RH SIDE MIRROR / BR                                                                    | 1.00 | 586.30       | 117.26     | 469.04     | L      | Y        | _____     |
| 3 FRONT RH OUTER DOOR GLASS MOULDING                                                           | 1.00 | 107.85       | 21.57 / BT | 86.28      | L      | Y        | _____     |
| 4 FRONT RH DOOR GLASS / CUT                                                                    | 1.00 | 705.68       | 141.14     | 564.54     | L      | Y        | _____     |
| 5 FRONT RH DOOR POWER WINDOW X REGULATOR                                                       | 1.00 | 350.10       | 70.02      | 280.08     | L      | Y        | _____     |
| 6 FRONT RH OUTER DOOR HANDLE X R                                                               | 1.00 | 68.90        | 13.78      | 55.12      | L      | Y        | _____     |
| 7 FRONT RH OUTER DOOR HANDLE COVER X R                                                         | 1.00 | 10.75        | 2.15       | 8.60       | L      | Y        | _____     |
| 8 REAR RH DOOR PANEL / 00                                                                      | 1.00 | 2,201.00     | 440.20     | 1,760.80   | L      | Y        | _____     |
| 9 REAR RH OUTER DOOR HANDLE X                                                                  | 1.00 | 68.90        | 13.78      | 55.12      | L      | Y        | _____     |
| 10 REAR RH OUTER DOOR HANDLE COVER X                                                           | 1.00 | 10.85        | 2.17       | 8.68       | L      | Y        | _____     |
| 11 REAR RH QUARTER PANEL / 00                                                                  | 1.00 | 2,171.50     | 434.30     | 1,737.20   | L      | Y        | _____     |
| 12 REAR RH DOOR GLASS X                                                                        | 1.00 | 705.68       | 141.14     | 564.54     | L      | Y        | _____     |

G-STAR-WI-ET-001-02-Rev00

## CLAIM DETAILS

| DESCRIPTION                                       | QTY  | QUOTED COSTS | DISCOUNT | DISC PRICE | IND | SUR.DISP | REV PRICE |
|---------------------------------------------------|------|--------------|----------|------------|-----|----------|-----------|
| 13 FRONT RH DOOR FRAME UPPER CHROME X<br>MOULDING | 1.00 | 39.80        | 7.96     | 31.84      | L   | Y        |           |
| 14 FRONT RH DOOR FRAME REAR BLACK CVT<br>MOULDING | 1.00 | 71.50        | 14.30    | 57.20      | L   | Y        |           |
| 15 FRONT RH DELTA GARNISH X                       | 1.00 | 102.30       | 20.46    | 81.84      | L   | Y        |           |
| 16 FRONT DOOR "COMFORT DELGRO" / nrc<br>STICKER   | 1.00 | 120.00       | 0.00     | 120.00     | S   | Y        |           |
| 17 FRONT AND REAR DOOR MOULDING CLIP X<br>SET     | 1.00 | 55.00        | 0.00     | 55.00      | S   | Y        |           |
| 18 REAR DOOR "GOOGLE PLAY STORE" / nrc<br>STICKER | 1.00 | 100.00       | 0.00     | 100.00     | S   | Y        |           |
| 19 REAR DOOR "COMFORT DELGRO" STICKER / nrc       | 1.00 | 100.00       | 0.00     | 100.00     | S   | Y        |           |
| 20 REAR WINDSCREEN PRIMER / nrc                   | 2.00 | 100.00       | 0.00     | 100.00     | S   | Y        |           |
| 21 REAR WINDSCREEN SEALANT / nrc                  | 3.00 | 150.00       | 0.00     | 150.00     | S   | Y        |           |
| 22 REAR QUARTER PANEL SEALANT / nrc               | 2.00 | 120.00       | 0.00     | 120.00     | S   | Y        |           |
| TOTAL:                                            |      | 10,202.11    | 1,891.43 | 8,310.68   |     |          |           |
| Supp- Rear Windscreen moulding \$101.42 / nrc (L) |      | 14,402.11    | 1,891.43 | 12,510.68  |     |          |           |
| TOTAL PARTS & LABOUR :                            |      |              |          |            |     |          |           |

EXCESS/LOADING:\$ 0.00

No. Of Day: 7 daysRE-SURVEY: BEFORE/AFTER PAINTING  
PART-BY-PART OR LUMP SUM: S\$DATE OF SURVEY: 11, 8, 22, 10.10.20 m.L  
SURVEYED BY: Steve CLKK

CONTACT NO: \_\_\_\_\_ FAX NO: \_\_\_\_\_

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX: