



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0019/22	Date of Report	: 27 May 22
To : Lim Spices Pte Ltd	Date of Request	: 5 May 22
111 North Bridge Road #21-01	Report requested by	: Lim Spices Pte Ltd
Peninsula Plaza	Date of Accident	: 4 May 22
Singapore 179098	Date of Inspection	: 5 May 22
	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: GBH 9293 X	Odometer Reading	: 64,380 km
Make	: Toyota	Carrying Capacity	: 3500 kg
Model	: Dyna Box Lorry (M)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2018	Air-Conditioner	: Yes
Colour	: White	Wing Mirror	: Yes
Engine Capacity	: 2,982 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: JTFAT35Y80K211664	Others	: Nil

TYRE CONDITION

Front Left	: 7mm	Front Right	: 7mm
Make	: Bridgestone	Make	: Bridgestone
Rear Left	: 8mm/8mm	Rear Right	: 8mm/8mm
Make	: Tourador	Make	: Tourador
Spare	:	Road Wheels Type	: Standard

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	15,316.58	14,458.28
Labour Charges :	3,800.00	3,150.00
Paint Work :	2,000.00	1,800.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	21,116.58	19,408.28

Reduction (S \$) : 5,616.58

Recommended Reserve (S \$) : 15,500.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at M/s. FA Autoworks Pte Ltd, 39 Woodlands Close #01-35 Mega@Woodlands, Singapore 737856

Follow-up inspection has been conducted.

Point of Impact

At the front and rear portion.

Damages

The front bumper, bumper bracket LH & RH, front headlamp LH & RH, front grille, front panel inner & outer, front corner panel LH & RH, front wiper panel, front wiper arm & nozzle LH, air-con cooling unit blower assy, washer tank, side mirror arm LH, rear end panel, tail lamp LH & RH, tail lamp bracket LH & RH, rear number plate panel & bracket, rear tail door LH & RH, rear tail door vertical bar LH & RH, metal box rear outer frame LH, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$19,408.28

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$15,500.00

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser



JEFFREY ONG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
To Supply :					
1pc. Front bumper	Dented	621.80	25	621.80	25
2pcs. Front bumper bracket LH & RH	Dented / Bent	470.00	25	470.00	25
1pc. Front bumper reinforcement	Dented / Repair	455.60	25	--	25
2pcs. Front bumper fog lamp cover LH & RH	Cracked	164.20	25	164.20	25
2pcs. Front headlamp LH & RH	Broken	1,957.60	25	1,957.60	25
1pc. Front grille	Cracked	595.20	25	595.20	25
1pc. Front grille LOGO emblem	Necessary	80.10	25	80.10	25
1pc. Front panel	Dented	1,194.30	25	1,194.30	25
1pc. Front panel DYNA emblem	Necessary	91.75	25	91.75	25
1pc. Front panel inner	Dented / Repair	--	25	--	25
2pcs. Front corner panel LH & RH	Cracked	558.60	25	558.60	25
1pc. Front wiper panel	Dented	429.10	25	429.10	25
2pcs. Front wiper nozzle LH & RH	LH Dented	174.40	25	87.20	25
2pcs. Front wiper arm LH & RH	LH Dented	203.06	25	101.53	25
1pc. Front windscreen glass rubber moulding	Necessary	369.40	25	369.40	25
1pc. Air-con cooling unit blower assy	Housing Cracked	2,674.00	25	2,674.00	25
1pc. Washer tank	Dented	139.30	25	139.30	25
1pc. Front side mirror arm LH	Bent	685.70	25	685.70	25
1pc. Front side mirror big (rectangle) LH	Refit	243.80	25	--	25
1pc. Front side mirror small (round) LH	Refit	189.60	25	--	25
1pc. Rear end panel	Dented	342.70	25	342.70	25
2pcs. Rear tail lamp LH & RH	Defaced	502.60	25	502.60	25
2pcs. Rear tail lamp bracket LH & RH	Dented / Bent	123.60	25	123.60	25
1pc. Rear number plate panel	Dented / Bent	228.60	25	228.60	25
1pc. Rear number plate bracket	Bent	67.10	25	67.10	25
Sub-Total :-		12,562.11		11,484.38	
Total Discount :-		3,140.53		2,871.10	
		9,421.58		8,613.28	
Special Nett Items :-					
1pc. Front number plate	Dented	50.00		50.00	
1set Front grille clips	Necessary	30.00		30.00	
1pc. Rear number plate	Dislodged / Missing	50.00		50.00	
1set Reverse sensor	Dented	300.00		250.00	
2pcs. Rear tail door LH & RH	Dented / Torn	3,500.00		3,500.00	
2pcs. Rear tail door vertical bar LH & RH (come with lock)	Dented / Bent	1,500.00		1,500.00	

Vehicle No : GBH 9293 X Toyota Dyna Box Lorry (M)

TP/0019/22


Workshop : FA Autoworks Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
1pc. Metal box rear outer frame LH	Dented	450.00		450.00	
1pc. 70 km/h sticker	Necessary	15.00		15.00	
Total For Parts :-		15,316.58		14,458.28	
Labour Charges :					
To dismantle, replace and panel beating affected parts.		2,500.00		2,200.00	
To remove/replace/refit front windscreen.		150.00		120.00	
To remove/replace/refit dashboard, meter instruments and etc.		350.00		250.00	
To remove/renew air-con, refill air-con gas and etc.		200.00		120.00	
To apply anti-rust on affected areas.		200.00		150.00	
To check wiring for front and rear portion.		100.00		60.00	
To diagnose and reset ECU system after repair.		300.00		250.00	
Spray Painting :					
To spray paint on affected areas.		2,000.00		1,800.00	
Grand Total :-		21,116.58		19,408.28	

Surveyed By : Jeffrey Ong




PRIORITY SERVICES



PRIORITY SERVICES






PRIORITY SERVICES




PRIORITY SERVICES














LES * PRIORITY SERVICES



LES * PRIORITY SERVICES




LES * PRIORITY SERVICES



LES * PRIORITY SERVICES






PRIORITY SERVICES



PRIORITY SERVICES



PRIORITY SERVICES



PRIORITY SERVICES



