

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007611/UVY3Q2**Date:** 18/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00154542100
Claimant Vehicle No :	SJL5118E	Insured Vehicle No :	YN3033R
Date of Loss:	03/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D205487/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5118E	Engine No:	FB20CE01207
Make & Model:	SUBARU XV, 2.0 (A)	Chassis No:	JF1GT7KL5KG060870
Reg. Date:	30/11/2019 (Man. Year: 2018)	Odometer:	26675 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,006.40	4,461.60	1,544.80	25.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,735.00	1,875.00	860.00	31.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,741.40	6,336.60	2,404.80	27.51
+ GST 7.00/7.00% (S\$)	611.90	443.56	168.34	27.51
Nett Amount (S\$)	9,353.30	6,780.16	2,573.14	27.51

INSPECTION

Date of Assignment:	12/08/2022	
Date Inspected:	11/08/2022	Inspected At: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2022)
Parts:	M1-SUV	SUBARU XV 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL5118E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	700.00 FL	*600.00 FL
2	1		*FRONT BUMPER WIPER HEADLAMP WIPER COVER	Twisted	63.00 FL	*63.00 FL
3	1		*FRONT WIPER HEADLAMP NOZZLE ASSY W/BACKET	Cracked	102.00 FL	*102.00 FL
4	2		*FRONT BUMPER SIDE RETAINER L&R	Bent	48.00 FL	*48.00 FL
5	1		*FRONT HEADLAMP LOWER BUMPER RETAINER LH	Bent	58.00 FL	*58.00 FL
6	1		*FRONT HEADLAMP ASSY LH	Cracked	2,550.00 FL	*2,550.00 FL
7	1		*FRONT BUMPER FOG LAMP ASSY W/BACKET	Cracked	355.00 FL	*355.00 FL
8	1		*FRONT BUMPER FOG LAMP GRILLE LH	Missing	85.00 FL	*85.00 FL
9	1		*FRONT BUMPER SPONGE	Torn	95.00 FL	*95.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	388.00 FL	*388.00 FL
11	1		*FRONT BUMPER TOP RUBBER	Necessary	48.00 FL	*48.00 FL
12	1		*FRONT FENDER LH	Dented / Bent	320.00 FL	*320.00 FL
13	1		*FRONT FENDER WHEEL ARCH GARNISH L&R (O/S Scratched)(Not Consistent With Impact)	N/S Deformed	336.00 FL	*168.00 FL
14	1		*FRONT FENDER INNER COWLING LH	Not Necessary	110.00 FL	*- FL
15	8		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	48.00 FL	*- FL
16	1		*FRONT FENDER TOP GARNISH LH	Not Necessary	36.00 FL	*- FL
17	3		*FRONT FENDER TOP GARNISH CLIPS	Not Necessary	18.00 FL	*- FL
18	1		*FRONT WIPER RESERVE TANK	Deformed	135.00 FL	*135.00 FL
19	1		*FRONT WIPER RESERVE TANK MOTOR	Not Necessary	89.00 FL	*- FL
20	1		*FRONT GRILLE ASSY	Cracked	172.00 FL	*172.00 FL
21	1		*FRONT GRILLE CHROME	Cracked	140.00 FL	*140.00 FL
22	1		*SET FRONT BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
23	1		*FRONT BUMPER LOWER SPOILER	Not fitted	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,596.00	5,527.00
- List Item Discount on L Items 10.00/20.00% (\$\$)	589.60	1,065.40
Total Parts (\$\$)	6,006.40	4,461.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL F/GRILLE ,F/HEADLAMP ,F/BUMPER,F/FENDER ,BUMPER ENFORCEMENT ,KNOCK HEADLAMP SUPPORT PANEL ,WHEEL HOUSE PANEL LH, F/FENDER RH AND RESTRAIGHTEN BODY & CHASSIS	New	1,130.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	RENEW AND RESET PAKRING SENSOR	New	80.00	50.00
5	RESET AIR BAG CONTROL UNIT	New	300.00	200.00
Gross Labour Cost (\$)			2,735.00	1,875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >