6/20/23, 11:55 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22007615/KYA3Q2

20/06/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210067584 **Claimant Vehicle** SHD5978E Insured Vehicle No: GBL3858K

No:

Date of Loss: 21/05/2022 Nature of Claim: TP Claim No: 7815109867SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD5978E**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) 2ZR2B64334 Engine No:

Reg. Date: 01/11/2018 (Man. Year: 2018) Chassis No: JTDKB3FU603075573

Colour: Metallic Pearl White/Red Odometer: 312251 km

Engine Capacity: 1798 cc Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: Firenza 7 mm Rear Left Side: Firenza 6 mm Front Right Side: Firenza 7 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,631.77	1,225.62	4,406.15	78.24
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,990.00	440.00	4,550.00	91.18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,621.77	1,665.62	8,956.15	84.32
	Approved Total (Overridden) (S\$)		1,330.00		
	Nett Amount (S\$)	10,621.77	1,330.00	9,291.77	87.48
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 10/08/2022

Trans-cab Auto Services Pte Ltd 10/08/2022 Inspected At: Date Inspected:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Manager: Adjuster: **KENNETH KONG** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

ο.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
	1		*COVER ,FRONT BUMPER	Buckled / Cracked	516.00 FL	*516.00 FL
	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.10 FL	*80.10 FL
	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Repair	716.60 FL	*- FL
	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
	1		*LAMP ASSY ,FOG ,RH	Cut	951.40 FL	*951.40 FL
	1		*UNIT ASSY ,HEADLAMP RH	*Check	2,637.60 FL	*- FL
	1		*COVER ,FRONT BUMPER HOLE ,RH	Serviceable	29.30 FL	*- FL
	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
0	1		*EMBLEM ASSY ,RADIATOR GRILLE	Serviceable	90.80 FL	*- FL
1	1		*GRILLE ,RADIATOR ,LOWER NO.1	Serviceable	170.10 FL	*- FL
2	1		*FENDER SUB-ASSY ,FRONT RH	Repair	977.80 FL	*- FL
3	1		*LINER ,FRONT FENDER ,RH	Serviceable	206.70 FL	*- FL
4	1		*FRONT FENDER EMBLEM RH	Not Necessary	54.60 FL	*- FL
5	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*65.00 FS
6	1		*FRT NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
7	1		*FRT BUMPER SIDE RETAINER CLIP	Not Necessary	65.00 FS	*- FS
8	1		*FENDER LINER CLIP	Not Necessary	75.00 FS	*- FS
=Fran	nchise	part. S=Spc	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	7,400.70	1,612.50
	- List Item Discount on L Items 25.00/25.00% (S\$)				1,768.93	386.88
				Total Parts (S\$)	5,631.77	1,225.62

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	220.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labou	r Cost (S\$)	4,990.00	440.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >