



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 40U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	NOT NECESSARY	250.00	-
10	FRONT BUMPER CLIPS (WCP)	NOT NECESSARY	18.00	-
1	FRONT LH FENDER (WCP)	BENT	360.00	360.00
1	FRONT LH FENDER TRIM GARNISH (WCP)	DEFORMED	72.00	72.00
1	FRONT LH FENDER PROTECTOR (WCP)	DEFORMED	38.00	38.00
1	FRONT LH MUDFLAP (WCP)	CUT	58.00	58.00
1	FRONT LH DOOR (WCP)	BENT	680.00	680.00
1	FRONT LH DOOR LH LOWER HINGE (WCP)	NOT NECESSARY	42.00	-
1	FRONT LH DOOR PROTECTOR (WCP)	CUT	146.00	146.00
1	FRONT LH FENDER SHIELD (WCP)	DEFORMED	114.00	114.00
1	FRONT LH SHOCK ABSORBER (WCP)	BENT	234.00	234.00
1	FRONT LH DRAG LINK (WCP)	BENT	78.00	78.00
1	FRONT LH ABS SENSER WIRE (WCP)	DISTORTED	198.00	198.00
1	FRONT LH KNUCKLE ARM (WCP)	BENT	264.00	264.00
1	FRONT LH KNUCKLE BEARING (WCP)	BENT	222.00	222.00
1	FRONT LH DRIVE SHAFT (WCP)	NOT NECESSARY	816.00	-
1	FRONT LH LOWER ARM (WCP)	BENT	210.00	210.00
1	FRONT LH LOWER ARM BALL JOINT (WCP)	BENT	84.00	84.00
1	FRONT LH CHASSIS MEMBER (NPA) (WCP)	NOT NECESSARY	-	-
1	FRT POWER STEERING RACK & PINION (WCP)	BENT	2,340.00	2,340.00
1	REAR LH DOOR (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
1	REAR LH DOOR PROTECTOR (WCP)	MISSING	96.00	96.00
1	LH LOCKER PANEL (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
COST PLUS 15%			948.00	779.10
			7,268.00	5,973.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT LH TYRE (NPA) (SN)	NOT NECESSARY	-	-
1	FRONT LH RIM (NPA) (SN)	DENTED	-	-
			-	-

Report Ref No. CS/GAI22007616/Tvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOWING FEE.		80.00	80.00
	RENEW UNDERCARRIAGE.		450.00	180.00
	WHEEL ALIGNMENT.		80.00	80.00
	SPRAY PAINTING.		1,180.00	660.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF REAR LH DOOR & LH LOCKER PANEL.		780.00	600.00
	TUFF COAT.		100.00	30.00
	WIRING.	NOT NECESSARY	35.00	-
			2,705.00	1,630.00
	GRAND TOTAL		9,973.00	7,603.10
	RECOMMENDED COST OF REPAIRS			7,603.10
	LESS EXCESS			-700.00
	NETT LIABILITY			6,903.10

Report Ref No. CS/GAI22007616/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.