#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.

Our File No: CS/AIS22007617/KVY3E2

79 Robinson Road #09-01 Singapore 068897 **Date:** 07/09/2022

**REFERENCE** 

Insured/Claimant: SG BUDGET CAR LEASING PTE LTD Policy No: SP2001630721

Date of Loss: 06/08/2022 Nature of Claim: OD Claim No: 202222006040SL

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMV6758M

Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FGKU024466

Reg. Date: 15/10/2020 (Man. Year: 2019) Chassis No: KMHD841CMLU035040

Colour: White Odometer: 45293 km

Engine Capacity: 1591 cc
Market Value/New Car Price: \$\$99,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Nexen 3 mm Rear Left Side: Nexen 2 mm
Front Right Side: Nexen 3 mm Rear Right Side: Nexen 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,881.30	4,988.50	4,892.80	49.52
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,765.00	1,600.00	2,165.00	57.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,646.30	6,588.50	7,057.80	51.72
	- Excess (S\$)	0.00	2,000.00	-2,000.00	
	(S\$)	13,646.30	4,588.50	9,057.80	66.38
	+ GST 7.00/7.00% (S\$)	955.25	321.20	634.05	66.38
	Nett Amount (S\$)	14,601.55	4,909.70	9,691.85	66.38

INSPECTION

Date of Assignment: 10/08/2022 Present Location: Ding Auto Pte Ltd (HQ)

Ding Auto Pte Ltd (HQ)

Date Inspected: 11/08/2022 Inspected At: 176 Sin M

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2022)

Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMV6758M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (WCP)	Torn	574.00 F	*470.00 F
2	1	*FRONT BONNET (WCP)	Buckled	949.00 F	*750.00 F
3	1	*FRONT REINFORCEMENT (WCP)	Bent	695.00 F	*230.00 F
4	1	*FRONT BUMPER SPONGE (WCP)	Missing	130.00 F	*60.00 F
5	1	*RADIATOR (WCP)	Bent	570.00 F	*300.00 F
6	1	*CONDENSER (WCP)	Bent	360.00 F	*250.00 F
7	1	*FRONT HEADLAMP LHS (WCP)	Cracked	1,398.00 F	*620.00 F
8	1	*FRONT HEADLAMP RHS (WCP)	Cracked	1,398.00 F	*550.00 F
9	1	*RADIATOR TOP GARNISH (WCP)	Missing	76.00 F	*60.00 F
10	1	*FRONT SUPPORT PANEL (WCP)	Cracked	300.00 F	*300.00 F
11	1	*FRONT GRILL (WCP)	Broken	250.00 F	*250.00 F
12	1	*FRONT BUMPER BRACKET LHS (WCP)	Cracked	67.00 F	*20.00 F
13	1	*FRONT BUMPER BRACKET RHS (WCP)	Cracked	67.00 F	*20.00 F
14	1	*BONNET INSULATOR (WCP)	Serviceable	75.00 F	*-F
15	1	*FRONT FOGLAMP LHS (WCP)	Serviceable	125.00 F	*-F
16	1	*FRONT FOGLAMP RHS (WCP)	Serviceable	125.00 F	*- F
17	1	*FRONT FOGLAMP GARNISH RHS (WCP)	Serviceable	45.00 F	*- F
18	1	*FRONT FOGLAMP GARNISH LHS (WCP)	Serviceable	45.00 F	*-F
19	1	*FAN CROWLING ASSY (WCP)	Cracked	587.00 F	*280.00 F
20	1	*RADIATOR TOP HOSE (WCP)	Punctured	52.00 F	*25.00 F
21	1	*RADIATOR BOTTOM HOSE	Serviceable	58.00 F	*-F
22	1	*BONNET HINGE LHS (WCP)	Distorted	50.00 F	*45.00 F
23	1	*BONNET HINGE RHS (WCP)	Distorted	50.00 F	*45.00 F
24	1	*FENDER INNER SHIELD LHS (WCP)	Serviceable	95.00 F	*-F
25	1	*FENDER INNER SHIELD RHS (WCP)	Serviceable	95.00 F	*- F
26	1	*ENGINE LOWER COVER (WCP)	Serviceable	70.00 F	*-F
27	1	*FRONT REINFORCEMENT METAL BRACKET LHS	Repair	135.00 F	*- F

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT REINFORCEMENT METAL (WCP)	BRACKET RHS Repair	135.00 F	*- F
1		*BONNET LOCK	Distorted	65.00 F	*65.00 F
1		*BONNET CATCH (WCP)	Repair	42.00 F	*- F
1		*HEADLAMP BRACKET LHS (WCP)	Cracked	30.00 F	*25.00 F
1		*HEADLAMP BRACKET RHS (WCP)	Cracked	30.00 F	*25.00 F
1		*RADIATOR GUIDE LHS (WCP)	Distorted	30.00 F	*30.00 F
1		*RADIATOR GUIDE RHS (WCP)	Distorted	30.00 F	*30.00 F
1		*AIR INTAKE GUIDE ASSY (WCP)	Serviceable	65.00 F	*-F
1		*FRONT CAR PLATE WITH FRAME (WCP)	Bent	50.00 F	*20.00 F
oleme	entary #1				
1		*AIR DUCT (WCP)	Cracked	65.00 F	*65.00 F
nchise	part.		,		
				•	4,535.00
			+ Margin on L,N Items 10.00/10.00% (S\$)	898.30	453.50
			Total Parts (S\$)	9,881.30	4,988.50
		Report was uns	ubmitted during this print-out.		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(WCP)  1 *BONNET LOCK (WCP)  1 *BONNET CATCH (WCP)  1 *HEADLAMP BRACKET LHS (WCP)  1 *HEADLAMP BRACKET RHS (WCP)  1 *RADIATOR GUIDE LHS (WCP)  1 *RADIATOR GUIDE RHS (WCP)  1 *AIR INTAKE GUIDE ASSY (WCP)  1 *FRONT CAR PLATE WITH FRAME (WCP)  Dlementary #1  1 *AIR DUCT (WCP)  nchise part.	1 *FRONT REINFORCEMENT METAL BRACKET RHS (WCP)  1 *BONNET LOCK (WCP)  1 *BONNET CATCH (WCP)  1 *HEADLAMP BRACKET LHS (Cracked (WCP)  1 *HEADLAMP BRACKET RHS (Cracked (WCP)  1 *RADIATOR GUIDE LHS (WCP)  1 *RADIATOR GUIDE RHS (WCP)  1 *AIR INTAKE GUIDE ASSY (WCP)  1 *FRONT CAR PLATE WITH FRAME (WCP)  Diementary #1  1 *AIR DUCT (WCP)  Cracked (WCP)  *AIR DUCT (WCP)  *Margin on L,N Items 10.00/10.00% (S\$)	*FRONT REINFORCEMENT METAL BRACKET RHS (WCP)

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	New	1,500.00	850.00
2	REMOVE AND REFIT CONDENSER/RADIATOR	New	150.00	100.00
3	REFILL AIRCON GAS	New	35.00	0.00
4	REFILL COOLANT	New	80.00	30.00
5	MOUNT WORKBENCH AND STRAIGHTEN CHASSIS ACCIDENT AREA	New	350.00	0.00
6	REPAIR/CHECK WIRING	New	120.00	20.00
7	ALIGN HEADLAMP AND TEST WIRING	New	80.00	0.00
8	TROUBLESHOOTING AND CLEAR FAULT CODE	New	250.00	0.00
9	SPRAY PAINT ACCIDENT AREA - FRONT BONNET INNER/OUTER, FRONT BUMPER, FENDER FLHS AND FENDER FRHS	New	1,200.00	600.00
	Gross Labour C		3,765.00	1,600.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >