

Merimen Repair Estimate

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001630721	Date of Loss:	08/08/2022
Vehicle Reg. No.:	SMV6758M	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SG BUDGET CAR LEASING PTE LTD		
Driver:	CHUA GLENDOLPH TENG YANG		
Year/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	15/10/2020
Vehicle Colour:	Silver		
Engine No:	G4FGKU024466	Chassis No:	KMHD841CMLU035040
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 6 days		
Present Location:	DING AUTO PTE LTD (HQ)		

Not within Warranty B4 paint ex \$2000

COST OF CLAIMS

	Amount
Parts	9,809.80
Miscellaneous Items	0.00
Labour	3,765.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,574.80
+ GST 7.00% (S\$)	950.24
Nett Amount (S\$)	14,525.04

This claim is handled by: DING SING HUI, KENNETH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Aug 2022)

Parts: 143 **HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: Ding Auto Pte Ltd/SMV6758M/10/08/2022 12:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	574.00 F ✓ 470
2	1		*FRONT BONNET	0.00	0.00	949.00 F ✓ 750
3	1		*FRONT REINFORCEMENT	0.00	0.00	695.00 F ✓ 230
4	1		*FRONT BUMPER SPONGE	0.00	0.00	130.00 F ✓ 60
5	1		*RADIATOR	0.00	0.00	570.00 F ✓ 300
6	1		*CONDENSER	0.00	0.00	360.00 F ✓ 250
7	1		*FRONT HEADLAMP LHS	0.00	0.00	1,398.00 F ✓ 620
8	1		*FRONT HEADLAMP RHS	0.00	0.00	1,398.00 F ✓ 550
9	1		*RADIATOR TOP GARNISH	0.00	0.00	76.00 F ✓ 60
10	1		*FRONT SUPPORT PANEL	0.00	0.00	300.00 F ✓
11	1		*FRONT GRILL	0.00	0.00	250.00 F ✓
12	1		*FRONT BUMPER BRACKET LHS *	0.00	0.00	67.00 F ✓ 20
13	1		*FRONT BUMPER BRACKET RHS	0.00	0.00	67.00 F ✓ 20
14	1		*BONNET INSULATOR	0.00	0.00	75.00 F X
15	1		*FRONT FOGLAMP LHS	0.00	0.00	125.00 F X
16	1		*FRONT FOGLAMP RHS	0.00	0.00	125.00 F X
17	1		*FRONT FOGLAMP GARNISH RHS	0.00	0.00	45.00 F X
18	1		*FRONT FOGLAMP GARNISH LHS	0.00	0.00	45.00 F X
19	1		*FAN CROWLING ASSY *	0.00	0.00	587.00 F ✓ 280
20	1		*RADIATOR TOP HOSE	0.00	0.00	52.00 F ✓ 25
21	1		*RADIATOR BOTTOM HOSE	0.00	0.00	58.00 F 7
22	1		*BONNET HINGE LHS	0.00	0.00	50.00 F ✓ 45
23	1		*BONNET HINGE RHS	0.00	0.00	50.00 F ✓ 45
24	1		*FENDER INNER SHIELD LHS	0.00	0.00	95.00 F X
25	1		*FENDER INNER SHIELD RHS	0.00	0.00	95.00 F X
26	1		*ENGINE LOWER COVER	0.00	0.00	70.00 F X
27	1		*FRONT REINFORCEMENT METAL BRACKET LHS	0.00	0.00	135.00 F X
28	1		*FRONT REINFORCEMENT METAL BRACKET RHS	0.00	0.00	135.00 F X
29	1		*BONNET LOCK	0.00	0.00	65.00 F ✓
30	1		*BONNET CATCH	0.00	0.00	42.00 F X
31	1		*HEADLAMP BRACKET LHS	0.00	0.00	30.00 F X 25
32	1		*HEADLAMP BRACKET RHS	0.00	0.00	30.00 F ✓ 25
33	1		*RADIATOR GUIDE LHS	0.00	0.00	30.00 F ✓
34	1		*RADIATOR GUIDE RHS	0.00	0.00	30.00 F ✓
35	1		*AIR INTAKE GUIDE ASSY	0.00	0.00	65.00 F X (19)
36	1		*FRONT CAR PLATE WITH FRAME	0.00	0.00	50.00 F ✓ 20

F=Franchise part.

supplementary;
Air Duct ✓ @ 865

Sub Total (\$\$) 8,918.00
+ Margin on L,N Items 10.00% (\$\$) 891.80

Total Parts (\$\$) 9,809.80

Ding Auto Pte Ltd/SMV6758M/10/08/2022 12:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Total: 24 items

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
Labour Items			
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	New	1,500.00
2	REMOVE AND REFIT CONDENSER/RADIATOR	New	150.00
3	REFILL AIRCON GAS	New	35.00
4	REFILL COOLANT	New	80.00
5	MOUNT WORKBENCH AND STRAIGHTEN CHASSIS ACCIDENT AREA	New	350.00
6	REPAIR/CHECK WIRING	New	120.00
7	ALIGN HEADLAMP AND TEST WIRING	New	80.00
8	TROUBLESHOOTING AND CLEAR FAULT CODE	New	250.00
9	SPRAY PAINT ACCIDENT AREA - FRONT BONNET INNER/OUTER, FRONT BUMPER, FENDER FLHS AND FENDER FRHS	New	1,200.00
Gross Labour Cost (S\$)			3,765.00

Ding Auto Pte Ltd/SMV6758M/10/08/2022 12:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ding Auto Pte Ltd

PARTS SUPPLEMENTARY & QUOTATION FORM

ATTENTION: Kenneth Fong / LKK	
VEHICLE NUMBER: SMV 6785 M	WORK ORDER NUMBER:
MAKE & MODEL: Hyundai Avante	OUR REFERENCE NUMBER:

S/NO	PART NUMBER	PART DESCRIPTION	QTY	UNIT PRICE	SURVEYOR REMARK	W/S REMARK
1		Air Duct	1	A 65.00 ✓	✓	
2						
3					65.00	
4						
5						
6						
7						
8		Labour :				
9		Straighten Front chassis	1	A 300.00 X	Add on	
10		Reinforcement bracket RH			A 250 in	
11		x LH			memen.	
12					15/08	
13						
14						
15						
16						
17						
18						



ESTIMATOR: Henry Lee

SURVEYOR: Kenneth Fong