

Merimen Repair Estimate

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (Own Damage)

Policy No: SP2001630721

Ref. No:

Date of 08/08/2022

Loss:

Driveable?

Party At UNKNOWN

Fault:

Third YES

Party

Involved?

Vehicle Reg. No.: SMV6758M

Driver Age/Info: / MALE

TP Injury Involved? NO

Insured/Claimant: SG BUDGET CAR LEASING PTE LTD

Driver: CHUA GLENDOLPH TENG YANG

Make/Model: HYUNDAI AVANTE, 1.6 (A)

Vehicle 15/10/2020

Reg. Date:

Vehicle Colour: Silver

Engine No: G4FGKU024466

Chassis KMHD841CMLU035040

No:

Odometer: 0 KM

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) 10 6 days

Not with claim
Repair B4 repair
ex @ 2000h

Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS

Amount

Parts

9,809.80

Miscellaneous Items

0.00

Labour

3,765.00

Paintwork Labour

0.00

Towing

0.00

Gross Total (S\$)

13,574.80

+ GST 7.00% (S\$)

950.24

Nett Amount (S\$)

14,525.04

is claim is handled by: DING SING HUI, KENNETH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Ding Auto Pte Ltd/SMV6758M/10/08/2022 12:05	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	Ln	0.00	0.00	*574.00 F	1
2	1		*FRONT BONNET	Bu	0.00	0.00	*949.00 F	1
3	1		*FRONT REINFORCEMENT	Ry	0.00	0.00	*695.00 F	1
4	1		*FRONT BUMPER SPONGE	niy	0.00	0.00	*130.00 F	1
5	1		*RADIATOR	Ry	0.00	0.00	*570.00 F	1
6	1		*CONDENSER	Ry	0.00	0.00	*360.00 F	1
7	1		*FRONT HEADLAMP LHS	CM	0.00	0.00	*1,398.00 F	1
8	1		*FRONT HEADLAMP RHS	CM	0.00	0.00	*1,398.00 F	1
9	1		*RADIATOR TOP GARNISH	niy	0.00	0.00	*76.00 F	1
10	1		*FRONT SUPPORT PANEL	CM	0.00	0.00	*300.00 F	1
11	1		*FRONT GRILL	Bu	0.00	0.00	*250.00 F	1
12	1		*FRONT BUMPER BRACKET LHS	CI	0.00	0.00	*67.00 F	7
13	1		*FRONT BUMPER BRACKET RHS	CM	0.00	0.00	*67.00 F	2
14	1		*BONNET INSULATOR	Sn	0.00	0.00	*75.00 F	X
15	1		*FRONT FOGLAMP LHS	Sn	0.00	0.00	*125.00 F	X
16	1		*FRONT FOGLAMP RHS		0.00	0.00	*125.00 F	7
17	1		*FRONT FOGLAMP GARNISH RHS	Sn	0.00	0.00	*45.00 F	X
18	1		*FRONT FOGLAMP GARNISH LHS	Sn	0.00	0.00	*45.00 F	λ
19	1		*FAN CROWLING ASSY		0.00	0.00	*587.00 F	7
20	1		*RADIATOR TOP HOSE	Bu	0.00	0.00	*52.00 F	1
21	1		*RADIATOR BOTTOM HOSE		0.00	0.00	*58.00 F	7
22	1		*BONNET HINGE LHS	DiY	0.00	0.00	*50.00 F	1
23	1		*BONNET HINGE RHS	DiY	0.00	0.00	*50.00 F	1
24	1		*FENDER INNER SHIELD LHS	Sn	0.00	0.00	*95.00 F	X
25	1		*FENDER INNER SHIELD RHS	Sn	0.00	0.00	*95.00 F	X
26	1		*ENGINE LOWER COVER		0.00	0.00	*70.00 F	7
27	1		*FRONT REINFORCEMENT METAL BRACKET LHS		0.00	0.00	*135.00 F	7
28	1		*FRONT REINFORCEMENT METAL BRACKET RHS		0.00	0.00	*135.00 F	7
29	1		*BONNET LOCK	DiY	0.00	0.00	*65.00 F	1
30	1		*BONNET CATCH	R	0.00	0.00	*42.00 F	λ
31	1		*HEADLAMP BRACKET LHS	Sn	0.00	0.00	*30.00 F	X
32	1		*HEADLAMP BRACKET RHS	CM	0.00	0.00	*30.00 F	1
33	1		*RADIATOR GUIDE LHS	DiY	0.00	0.00	*30.00 F	7
34	1		*RADIATOR GUIDE RHS	DiY	0.00	0.00	*30.00 F	7
35	1		*AIR INTAKE GUIDE ASSY	Sn	0.00	0.00	*65.00 F	X
36	1		*FRONT CAR PLATE WITH FRAME	Bu	0.00	0.00	*50.00 F	1

Franchise part.

Sub Total (\$\$) 8,918.00
+ Margin on L,N Items 10.00% (\$\$) 891.80

Total Parts (\$\$) 9,809.80

Ding Auto Pte Ltd/SMV6758M/10/08/2022 12:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Labour

No Particulars

Labour Items	Lab.Type	Amount
1 PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	New	1,500.00
2 REMOVE AND REFIT CONDENSER/RADIATOR	New	150.00
3 REFILL AIRCON GAS	New	35.00
4 REFILL COOLANT	New	80.00
5 MOUNT WORKBENCH AND STRAIGHTEN CHASSIS ACCIDENT AREA	New	350.00
6 REPAIR/CHECK WIRING	New	120.00
7 ALIGN HEADLAMP AND TEST WIRING	New	80.00
8 TROUBLESHOOTING AND CLEAR FAULT CODE	New	250.00
9 SPRAY PAINT ACCIDENT AREA - FRONT BONNET INNER/OUTER, FRONT BUMPER, FENDER FLHS AND FENDER FRHS	New	1,200.00
Gross Labour Cost (S\$)		3,765.00

Ding Auto Pte Ltd/SMV6758M/10/08/2022 12:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: