

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III22007618/KCY3E2**Date:** 22/03/2023REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D18MFL0003414_03

Date of Loss: 19/07/2022

Nature of Claim: OD

Claim No: MFL2022D0003854

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMY6064R**

Make & Model: TOYOTA NOAH HYBRID, 1.8 (A)

Engine No: 2ZR0F41904

Reg. Date: 17/03/2021 (Man. Year: 2020)

Chassis No: ZWR800439098

Colour: Metallic Black

Odometer: 121805 km

Engine Capacity: 1797 cc

Market Value/New Car Price: S\$158,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Davanti 9 mm

Rear Left Side: Davanti 8 mm

Front Right Side: Davanti 9 mm

Rear Right Side: Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,962.50	4,277.55	1,684.95	28.26
Miscellaneous Items	61.00	61.00	0.00	0.00
Labour	1,700.00	1,020.00	680.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,723.50	5,358.55	2,364.95	30.62
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	7,723.50	3,858.55	3,864.95	50.04
+ GST 7.00/8.00% (S\$)	540.65	308.68	231.97	42.91
Nett Amount (S\$)	8,264.15	4,167.23	4,096.92	49.57

INSPECTION

Date of Assignment: 11/08/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)

Date Inspected: 11/08/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)

205 Braddell Road
Singapore 579701

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY6064R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Buckled	1,152.70 FL	*1,152.70 FL
2	1		*FRT LH HEADLAMP	Mtg Cracked	3,606.30 FL	*3,606.30 FL
3	1		*FRT BONNET	Repair	926.00 FL	*- FL
4	1		*FRT BUMPER	Bent	845.00 FL	*845.00 FL
5	1		*FRT BUMPER LH RETAINER	Distorted	99.40 FL	*99.40 FL
6	1		*FRT BUMPER GRILLE	Serviceable	1,099.30 FL	*- FL
7	1		*FRT LH FOGLAMP GARNISH	Serviceable	113.50 FL	*- FL
8	1		*FRT HEADLAMP CHROME MOULDING	Serviceable	107.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,950.00	5,703.40
- List Item Discount on L Items 25.00/25.00% (S\$)	1,987.50	1,425.85
Total Parts (S\$)	5,962.50	4,277.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			61.00	61.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit LH affected area	New	800.00	400.00
2	To putty & respray on Lh affected area	New	800.00	600.00
3	To check wiring, focus headlamp	New	100.00	20.00
Gross Labour Cost (\$\$)			1,700.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >