

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007621/EVCE2**Date:** 30/11/2022**REFERENCE**

Insured/Claimant:	TEE GEOK CHENG	Policy No:	7210085013	
Date of Loss:	04/08/2022	Nature of Claim:	OD	Claim No: 5925761771SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU9009P	Engine No:	DEM028171
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF4XMA021527
Reg. Date:	30/07/2021 (Man. Year: 2020)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,929.00	30,389.68	19,539.32	39.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,922.00	12,162.00	4,760.00	28.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,851.00	42,551.68	24,299.32	36.35
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	66,301.00	42,001.68	24,299.32	36.65
+ GST 7.00/7.00% (S\$)	4,641.07	2,940.12	1,700.95	36.65
Nett Amount (S\$)	70,942.07	44,941.80	26,000.27	36.65

INSPECTION

Date of Assignment:	11/08/2022	
Date Inspected:	10/08/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	13.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	2,377.00 FS	*1,901.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	1	*FRONT BUMPER SECURING STRIP (2PCS)	Bent (1pc only)	79.00 FS	*63.20 FS
4	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT	Broken	293.00 FS	*234.00 FS
6	1	*FRONT BUMPER AIR GUIDE - RH	Crushed	51.00 FS	*40.08 FS
7	1	*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	293.00 FS	*- FS
8	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	151.00 FS	*120.40 FS
9	1	*FRONT BUMPER AIR GUIDE GRILLE TRIM - RH	Cut	54.00 FS	*42.64 FS
10	1	*RADIATOR GRILLE	Not Necessary	1,754.00 FS	*- FS
11	1	*FRONT BUMPER GUIDE SECTION - RH	Broken	41.00 FS	*32.24 FS
12	1	*FRONT BUMPER FOAM FILLER PIECE	Broken	212.00 FS	*169.20 FS
13	1	*FRONT BUMPER CARRIER	Bent	899.00 FS	*719.20 FS
14	1	*FRONT BUMPER BRACKET - RH	Not Necessary	254.00 FS	*- FS
15	1	*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
16	1	*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
17	1	*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
18	1	*FRONT BUMPER BRACKET	Broken	154.00 FS	*122.80 FS
19	2	*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
20	4	*POP RIVET	Necessary	4.00 FS	*2.88 FS
21	2	*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	532.00 FS	*- FS
22	4	*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
23	1	*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
24	1	*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
25	1	*FRONT SPRING SHACKLE - RH	Not Necessary	33.00 FS	*- FS
26	1	*FRONT FENDER - RH	Dented	1,227.00 FS	*981.60 FS
27	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	225.00 FS	*- FS
28	1	*FRONT FENDER CLOSING ELEMENT - RH	Necessary	81.00 FS	*64.24 FS
29	1	*FRONT FENDER BRACKET - RH	Bent	41.00 FS	*32.72 FS
30	1	*FRONT FENDER BRACE - RH	Not Necessary	55.00 FS	*- FS
31	7	*POP RIVET	Necessary	27.00 FS	*21.28 FS
32	1	*FRONT FENDER BRACKET - RH	Not Necessary	36.00 FS	*- FS
33	1	*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
34	1	*FRONT FENDER WHEEL HOUSING LINER- RH	Cracked	262.00 FS	*209.60 FS
35	1	*FRONT AND REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	149.00 FS	*119.20 FS
36	1	*FRONT WHEEL SPOILER - RH	Crushed	82.00 FS	*65.12 FS
37	1	*FRONT WHEEL SPOILER TRIM - RH	Broken	40.00 FS	*32.00 FS
38	1	*FRONT FENDER TOP COVER - RH	Necessary	35.00 FS	*27.52 FS
39	1	*HEADLAMP COVER - RH	Broken	49.00 FS	*38.64 FS
40	1	*BONNET	Dented	3,425.00 FS	*2,740.00 FS
41	1	*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
42	2	*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
43	3	*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
44	1	*FRONT FENDER INNER COVER - RH	Not Necessary	68.00 FS	*- FS
45	1	*BONNET STRIKER - RH	Not Necessary	56.00 FS	*- FS
46	1	*BONNET LOCK	Not Necessary	228.00 FS	*- FS
47	1	*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
48	1	*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
49	1	*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
50	1	*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
51	1	*HEADLIGHT - RH	Broken	8,172.00 FS	*6,537.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
53	3	*HEADLIGHT COMPENSATING PIECE	Missing	137.00 FS	*108.00 FS
54	1	*LIFT CYLINDER - RH	Broken	231.00 FS	*184.40 FS
55	1	*LIFT CYLINDER BRACKET	Broken	7.00 FS	*5.44 FS
56	1	*LIFT CYLINDER CORRUGATED PIPE - LONG	Not Necessary	107.00 FS	*- FS
57	1	*LIFT CYLINDER CORRUGATED PIPE - SHORT	Not Necessary	53.00 FS	*- FS
58	1	*LOCK CARRIER	Broken	1,127.00 FS	*901.60 FS
59	1	*RADIATOR COOLANT REGULATOR SUPPORT - RH	Not Necessary	43.00 FS	*- FS
60	1	*AIR COOLER CHARGE	Not Necessary	654.00 FS	*- FS
61	1	*AIR COOLER CHARGE PRESSURE HOSE - RH	Not Necessary	413.00 FS	*- FS
62	1	*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
63	1	*TEMP SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
64	1	*RADIATOR	Not Necessary	1,013.00 FS	*- FS
65	6	*COOLANT	Necessary	297.00 FS	*237.12 FS
66	1	*RADIATOR AIR GUIDE - RH	Not Necessary	51.00 FS	*- FS
67	3	*RADIATOR AIR GUIDE - LH / RH / UPPER	Not Necessary	57.00 FS	*- FS
68	1	*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
69	1	*INTAKE AIR DUCT - RH	Not Necessary	25.00 FS	*- FS
70	1	*INTAKE AIR DUCT GUIDE	Not Necessary	61.00 FS	*- FS
71	1	*INTAKE AIR DUCT HOSE	Not Necessary	110.00 FS	*- FS
72	1	*INTAKE AIR DUCT FILTER	Broken	418.00 FS	*334.40 FS
73	1	*AIR MASS METER	Not Necessary	629.00 FS	*- FS
74	1	*FRONT WHEEL ALUMINIUM RIM	Cut	1,292.00 FS	*1,033.60 FS
75	1	*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
76	1	*FRONT WINDOW TRIM STRIP CHROME - RH	Not Necessary	344.00 FS	*- FS
77	1	*FRONT WINDOW TRIM STRIP GUIDE HIGH CHROME	Not Necessary	287.00 FS	*- FS
78	1	*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
79	1	*SUNDRIES	Necessary	500.00 FS	*304.96 FS
80	1	*FRONT WISHBONE LINK-RH (Supplementary)	Bent	605.00 FS	*483.60 FS
81	1	*FRONT SUSPENSION GUIDE-RH LOWER (Supplementary)	Bent	1,057.00 FS	*845.60 FS
82	1	*FRONT SUSPENSION GUIDE-RH UPPER (Supplementary)	Bent	575.00 FS	*460.00 FS
83	1	*FRONT SUSPENSION GUIDE-RH UPPER (Supplementary)	Bent	575.00 FS	*460.00 FS
84	1	*FRONT WHEEL BEARING HOUDING-RH (Supplementary)	Bent	1,070.00 FS	*856.00 FS
85	1	*SWIVEL JOINT-RH (Supplementary)	Bent	214.00 FS	*170.80 FS
86	1	*FRONT WHEEL HUB-RH (Supplementary)	Necessary	499.00 FS	*399.20 FS
87	1	*WHEEL BEARING-RH (Supplementary)	Necessary	273.00 FS	*218.40 FS
88	1	*FRONT SUSPENSION FORK RH (Supplementary)	Bent	293.00 FS	*234.00 FS
89	1	*FRONT COUPLING ROD-RH (Supplementary)	Bent	129.00 FS	*103.20 FS
90	1	*FRONT ANTI-ROLL BAR (Supplementary)	Bent	478.00 FS	*382.40 FS
91	1	*FRONT GAS SHOCK ABSORBER-RH (Supplementary)	Bent	332.00 FS	*265.60 FS
92	1	*STEERING GEAR (Supplementary)	Bent	7,318.00 FS	*5,854.40 FS
93	1	*FRONT TIE ROD END-RH (Supplementary)	Bent	217.00 FS	*173.60 FS
94	1	*FRONT SUBFRAME (Supplementary)	Bent	2,096.00 FS	*1,676.80 FS
95	1	*ENGINE MOUNTING (Supplementary)	Not Necessary	420.00 FS	*- FS
96	1	*ENGINE MOUNTING CONSOLE-RH (Supplementary)	Not Necessary	523.00 FS	*- FS

Report was unsubmitted during this print-out.

11/30/22, 2:03 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	49,929.00	30,389.68
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR	New	280.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT AND RHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	3,250.00
7	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT AND RHS FRONT DOOR	New	4,500.00	2,470.00
8	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO REMOVE AND RENEW RHS FRONT SUSPENSION ASSY WITH SUBFRAME (Supplementary)	New	2,400.00	2,400.00
Gross Labour Cost (\$\$)			16,922.00	12,162.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >