

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22007624/KNY3E2**Date:** 09/11/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002033592

**Claimant Vehicle No :** GBE751R**Insured Vehicle No :** GBJ5099G

Date of Loss: 05/08/2022

Nature of Claim: TP Claim No: 281490

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBE751R**

Make &amp; Model: KIA K2500 6M/T, 2.5 D (M)

Engine No: D4CBF669203

Reg. Date: 24/08/2015 (Man. Year: 2014)

Chassis No: KNCSJX76LF7948244

Colour: White

Odometer: 214376 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size: 165R12X8 (D)

Front Left Side: Yokohama 3 mm

Rear Left Side: Yokohama 9/9 mm

Front Right Side: Yokohama 3 mm

Rear Right Side: Yokohama 9/9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,061.40	1,491.00	1,570.40	51.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	950.00	580.00	37.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,591.40</b>	<b>2,441.00</b>	<b>2,150.40</b>	<b>46.84</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,900.00</b>		
<b>(\$\$)</b>	4,591.40	1,900.00	2,691.40	58.62
<b>+ GST 7.00/7.00% (\$\$)</b>	321.40	133.00	188.40	58.62
<b>Nett Amount (\$\$)</b>	<b>4,912.80</b>	<b>2,033.00</b>	<b>2,879.80</b>	<b>58.62</b>

INSPECTION

Date of Assignment: 11/08/2022

Date Inspected: 07/09/2022 Inspected At:

Tropical Success Auto Care (HQ)  
BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2  
Singapore 569535

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Oct 2022)	
<b>Parts:</b>	N/A	KIA K2500 6M/T 2.5 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE751R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Bent	1,889.00 FL	*1,150.00 FL
2	1		*REAR GATE 70KM/H STICKER	Necessary	11.00 FL	*11.00 FL
3	1		*REAR GATE 13 PAX STICKER	Necessary	11.00 FL	*11.00 FL
4	2		*REAR GATE HINGE	Repair	432.00 FL	*- FL
5	1		*REAR TAIL LAMP	O/S Cracked / N/S Serviceable	594.00 FL	*155.00 FL
6	1		*REAR TAIL LAMP PANEL	O/S Bent / N/S Repair	486.00 FL	*243.00 FL
7	1		*REAR REVERSING SENSOR	Cracked	288.00 FS	*200.00 FS
8	1		*REAR LICENSE SMART PLATE & CASING	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,746.00</b>	<b>1,805.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	684.60	314.00
<b>Total Parts (\$\$)</b>	<b>3,061.40</b>	<b>1,491.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND TRANSFER REAR GATE NECESSARY ATTACHMENT SPART PART ITEMS }	New	600.00	450.00
2	REMOVE AND REFIT REAR GATE, REAR GATE HINGES, REAR TAIL LAMPS, REAR TAIL LAMP PANELS, REAR REVERSING SENSORS }	New	0.00	0.00
3	HEAD / WELD / BEATING / PULL / STRAIGHTEN / ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	0.00	0.00
4	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS	New	80.00	20.00
5	UNDER COATING ON REAR DAMAGED PORTION	New	150.00	30.00
6	PUTTY / PRIMER APPLICATION, SPRAY PAINTING REAR GATE, REAR GATE HINGES, REAR TAIL LAMP PANELS, REAR BUMPER REVERSING SENSORS	New	600.00	400.00
7	DIAGNOSTIC AND RESET REAR REVERSING SENSOR FAULT ERROR BY HHT	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,530.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >