

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007625/APA3Q2**Date:** 27/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800154322
Claimant Vehicle No :	SJR5499Z	Insured Vehicle No :	SMG5756D
Date of Loss:	10/08/2022	Nature of Claim:	TP
		Claim No:	1319943111SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR5499Z		
Make & Model:	KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A)	Engine No:	G4FC9H264200
Reg. Date:	29/06/2009 (Man. Year: 2009)	Chassis No:	KNAFH221395086838
Colour:	Black	Odometer:	361578 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,753.01	2,659.90	4,093.11	60.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	1,380.00	2,250.00	61.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,383.01	4,039.90	6,343.11	61.09
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	10,383.01	3,200.00	7,183.01	69.18
+ GST 8.00/8.00% (\$\$)	830.64	256.00	574.64	69.18
Nett Amount (\$\$)	11,213.65	3,456.00	7,757.65	69.18
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,823.45		
Global Sum Settlement (\$\$)		3,800.00		

INSPECTION

Date of Assignment:	10/08/2022		
Date Inspected:	10/08/2022	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	908.60 FL	*788.00 FL
2	1		*BONNET INNER LOCK	Not Necessary	125.60 FL	*- FL
3	1		*BONNET LOCK CABLE	Not Necessary	85.00 FL	*- FL
4	2		*BONNET HINGES	Not Necessary	131.60 FL	*- FL
5	1		*FRONT BUMPER	Distorted	705.80 FL	*562.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	345.80 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Cracked	185.60 FL	*120.00 FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	105.80 FL	*- FL
10	1		*FRONT BUMPER NUMBER PLATE BASE	Not Necessary	85.20 FL	*- FL
11	1		*FRONT BUMPER FOG LAMPS	Cracked	198.60 FL	*198.60 FL
12	1		*FRONT BUMPER FOG LAMPS COVER	Deformed	98.70 FL	*98.70 FL
13	1		*FRONT GRILLE	Not Necessary	345.80 FL	*- FL
14	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	168.90 FL	*- FL
15	1		*FRONT GRILLE BADGE	Not Necessary	48.00 FL	*- FL
16	1		*SET FRONT GRILLE CLIPS	Not Necessary	38.00 FL	*- FL
17	1		*HEADLAMPS	Cracked	508.90 FL	*508.90 FL
18	1		*HEADLAMPS BOTTOM RETAINERS	Not Necessary	85.90 FL	*- FL
19	2		*FRONT WIPER GARNISH SIDE RUBBER	Not Necessary	91.60 FL	*- FL
20	1		*FRONT FENDER	Repair	398.70 FL	*- FL
21	1		*FRONT FENDER INNER COWLING	Not Necessary	165.20 FL	*- FL
22	1		*SUPPORT PANEL	Cracked	569.80 FL	*569.80 FL
23	1		*BRACE PANEL	Not Necessary	78.90 FL	*- FL
24	1		*HORNS	Not Necessary	120.00 FL	*- FL
25	1		*RADIATOR	Not Necessary	792.00 FL	*- FL
26	1		*AIR CON CONDENSER	Not Necessary	852.00 FL	*- FL
27	1		*FRONT NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
28	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
29	1		*FRONT BUMPER SIDE RETAINERS (LH)	Damaged	68.90 FL	*35.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,488.90	2,951.00
- List Item Discount on L Items 10.00/10.00% (S\$)	735.89	291.10
Total Parts (S\$)	6,753.01	2,659.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	800.00
2	SPRAY PAINTING	New	1,600.00	400.00
3	CHECK WIRING ON HEADLAMP	New	100.00	30.00
4	ANTI RUST	New	180.00	30.00
5	REMOVE AND INSTALL AIR CON	New	150.00	120.00
Gross Labour Cost (S\$)			3,630.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >