

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22007628/UPA3Q2**Date:** 17/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070055229
<b>Claimant Vehicle No :</b>	SLE7197B	<b>Insured Vehicle No :</b>	GBJ4678S
Date of Loss:	10/08/2022	Nature of Claim:	TP
		Claim No:	2361127469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLE7197B</b>	Engine No:	274AE041544A
Make & Model:	INFINITI Q50, 2.0 T (R18) EU6 NAV (A)	Chassis No:	JN1BCAV37Z0480757
Reg. Date:	29/07/2016 (Man. Year: 2016)	Odometer:	103978 km
Colour:	Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	50,453.10	19,751.40	30,701.70	60.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,820.00	1,880.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>55,153.10</b>	<b>22,571.40</b>	<b>32,581.70</b>	<b>59.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>18,000.00</b>		
	(S\$)	55,153.10	18,000.00	37,153.10
<b>+ GST 7.00/7.00% (S\$)</b>	3,860.72	1,260.00	2,600.72	67.36
<b>Nett Amount (S\$)</b>	<b>59,013.82</b>	<b>19,260.00</b>	<b>39,753.82</b>	<b>67.36</b>
<b>+ Car Rental (9.0 x S\$150.00/day) (S\$)</b>		1,350.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>20,612.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>20,000.00</b>		

INSPECTION

Date of Assignment:	11/08/2022		Fastech Auto Pte Ltd (HQ)
Date Inspected:	11/08/2022	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
			Singapore 417883
Estimated Period of Repair:	8.0 days		

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**MARKET VALUE**

Market Value: \$73K(est) less LTA Rebate: \$46,038.00(est) = Nett Value  
:\$26,962.00(est)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Buckled	2,055.00 F	*1,800.00 FL
2	1		*BONNET INNER CENTRE SEAL	Torn	182.00 F	*115.00 FL
3	2		*BONNET HINGES	Bent / Twisted	760.00 F	*600.00 FL
4	1		*BONNET INSULATOR	Not Necessary	380.00 F	*- FL
5	1		*SET BONNET INSULATOR CLIPS	Necessary	80.00 F	*60.00 FL
6	1		*BONNET INNER LOCK	Twisted	650.00 F	*225.00 FL
7	1		*BONNET LOCK CABLE	Not Necessary	220.00 F	*- FL
8	1		*FRONT BUMPER	Distorted	2,297.00 F	*1,350.00 FL
9	2		*FRONT BUMPER SIDE RETAINERS	Cracked / Bent	500.00 F	*115.00 FL
10	1		*FRONT BUMPER CENTRE GRILLE	Torn	420.00 F	*245.00 FL
11	1		*FRONT BUMPER LOWER CENTRE GRILLE	Torn	399.00 F	*195.00 FL
12	1		*FRONT BUMPER SPONGE	Torn	416.00 F	*182.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	1,115.00 F	*635.00 FL
14	1		*FRONT BUMPER REINFORCEMENT LOWER BRACKET	Twisted	350.00 F	*302.00 FL
15	1		*FRONT BUMPER DAY LIGHT LAMP N/S	Broken / Missing	1,100.00 F	*380.00 FL
16	1		*FRONT BUMPER UNDER COVER	Torn	880.00 F	*320.00 FL
17	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	60.00 F	*45.00 FL
18	1		*FRONT BUMPER STIFFENER N/S	Distorted	90.00 F	*90.00 FL
19	1		*FRONT BUMPER FINISHER N/S	Distorted	135.00 F	*115.00 FL
20	1		*FRONT FOG LAMP N/S	Broken	520.00 F	*395.00 FL
21	1		*FRONT FOG LAMP GARNISH N/S	Torn	335.00 F	*188.00 FL
22	1		*FRONT BUMPER TOP RUBBER	Torn	120.00 F	*102.00 FL
23	1		*FRONT BUMPER TOP RETAINER	Distorted	182.00 F	*165.00 FL
24	1		*FRONT GRILLE ASSY	Cracked	980.00 F	*785.00 FL
25	1		*SET FRONT GRILLE PARKING CAMERA	Not Necessary	1,850.00 F	*- FL
26	1		*FRONT SIGNAL LAMP N/S	Cracked	245.00 F	*230.00 FL
27	1		*HEADLAMPS	N/S Broken	9,856.00 F	*3,066.00 FL
28	1		*HEADLAMP LOWER BRACKETS	N/S Cracked	500.00 F	*145.00 FL
29	1		*HEADLAMP NOZZLE COVER N/S	Not fitted	82.00 F	*- FL
30	1		*HEADLAMP NOZZLE N/S	Not fitted	350.00 F	*- FL
31	1		*FRONT AIR GUIDE TOP N/S	Torn	98.00 F	*98.00 FL
32	1		*FRONT AIR GUIDES	N/S Torn	870.00 F	*300.00 FL
33	1		*FRONT SUPPORT PANEL TOP COVER	Distorted	199.00 F	*192.00 FL
34	1		*FRONT SUPPORT PANEL	Distorted	1,955.00 F	*1,560.00 FL
35	1		*FRONT SUPPORT LOWER PANEL N/S	Distorted	200.00 F	*152.00 FL
36	1		*FRONT SUPPORT PANEL CENTRE BRACKET	Twisted	150.00 F	*100.00 FL
37	1		*AIR CON CONDENSER	Bent / Twisted	1,540.10 F	*1,480.00 FL
38	1		*RADIATOR	Serviceable	1,988.00 F	*- FL
39	1		*INTER COOLER	Not Necessary	1,450.00 F	*- FL
40	1		*FRONT BRACE PANEL	Not Necessary	885.00 F	*- FL
41	1		*FRONT FENDER N/S	Distorted	1,200.00 F	*820.00 FL
42	1		*FRONT FENDER INNER SHIELD N/S	Torn	313.00 F	*245.00 FL
43	1		*FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
44	1		*FRONT FENDER INNER TOP GARNISH N/S	Torn	165.00 F	*164.00 FL
45	1		*FRONT DOOR N/S	Repair	2,880.00 F	*- FL
46	1		*WASHER TANK NECK	Deformed	145.00 F	*105.00 FL
47	1		*WASHER TANK	Distorted	288.00 F	*230.00 FL
48	1		*WASHER TANK MOTOR	Jammed	280.00 F	*205.00 FL
49	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*60.00 FL
50	1		*FRONT LICENCE PLATE W/HOLDER	Not Necessary	150.00 F	*- FL
51	1		*FRONT PDC SENSORS	N/S Shorted	440.00 F	*195.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT DISTANCE SENSOR N/S	Shorted	250.00 F	*195.00 FL
53	1		*BOL AIR CON OIL	Necessary	50.00 F	*50.00 FL
54	1		*BOL RADIATOR COOLANT	Necessary	50.00 F	*50.00 FL
55	1		*ROCKER PANEL GARNISH N/S	Torn	988.00 F	*820.00 FL
56	1		*SET ROCKER PANEL GARNISH CLIPS N/S	Necessary	50.00 F	*50.00 FL
57	1		*FRONT SHOCK ABSORBER N/S	Serviceable	845.00 F	*- FL
58	1		*FRONT LOWER ARM N/S	Bent	755.00 F	*600.00 FL
59	1		*FRONT KNUCKLE ARM N/S	Warped	920.00 F	*895.00 FL
60	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	450.00 F	*380.00 FL
61	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,180.00 F	*- FL
62	2		*FRON ENGINES	Not Necessary	900.00 F	*- FL
63	1		*FRON ENGINE REAR	Not Necessary	380.00 F	*- FL
64	1		*FRONT SPORT RIM N/S	Warped	1,200.00 F	*1,100.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>50,453.10</b>	<b>21,946.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	0.00	2,194.60
<b>Total Parts (S\$)</b>	<b>50,453.10</b>	<b>19,751.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REFILL AIR CON GAS	New	120.00	100.00
3	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	50.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	100.00
5	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	350.00	120.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	New	580.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	1,000.00
9	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,300.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,700.00</b>
				<b>2,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >