

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22007630/KVY3M4**Date:** 20/12/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001972238

Claimant Vehicle No : GBC6470Y**Insured Vehicle No :** GBK8269H

Date of Loss: 10/08/2022

Nature of Claim: TP

Claim No: 281591

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC6470Y**

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2299810

Reg. Date: 20/06/2013 (Man. Year: 2013)

Chassis No: JTFHT02P100117209

Colour: Silver

Odometer: 352585 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size: 195 R15X8

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,262.04	4,469.62	792.42	15.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,400.00	300.00	17.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,962.04	5,869.62	1,092.42	15.69
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	6,962.04	4,700.00	2,262.04	32.49
+ GST 7.00/7.00% (S\$)	487.34	329.00	158.34	32.49
Nett Amount (S\$)	7,449.38	5,029.00	2,420.38	32.49

INSPECTION

Date of Assignment: 11/08/2022

Date Inspected: 11/08/2022 Inspected At:

CHENG HOE MOTOR PL
BLK 1019 YISHUN IND. PARK A
#01-374/382 SINGAPORE 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Dec 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6470Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	397.20 FL	*397.20 FL
2	1		*REAR BUMPER SIDE RETAINERS	N/s Distorted	45.60 FL	*22.80 FL
3	6		*REAR BUMPER CLIPS	Necessary	22.80 FL	*22.80 FL
4	1		*REAR TAILGATE	Bent	2,154.20 FL	*2,051.60 FL
5	1		*TAILGATE LOGO	Necessary	66.70 FL	*66.70 FL
6	1		*TAILGATE STICKER (TOYOTA HIACE)	Necessary	52.60 FL	*52.60 FL
7	1		*TAILGATE OUTER HANDLE	Dented/Cut	143.10 FL	*143.10 FL
8	1		*TAILGATE INNER LOCK	Dented	323.60 FL	*323.60 FL
9	1		*REAR WINDSCREEN GLASS	Shattered	1,297.10 FL	*1,191.00 FL
10	1		*REAR END PANEL OUTER	Buckled	309.80 FL	*309.80 FL
11	1		*REAR END PANEL TOP BEAM	Warped	114.30 FL	*114.30 FL
12	1		*RH TAILLAMP	Cracked	324.70 FL	*324.70 FL
13	1		*REAR NUMBER PLATE LAMP	Serviceable	79.50 FL	*- FL
14	1		*REAR ROOM MIRROR	Serviceable	524.10 FL	*- FL
15	1		*LH TAIL LAMP	Cut	324.70 FL	*324.70 FL
16	1		*TAILGATE INNER RUBBER (\$381.90) (50%)	Cut	357.04 FS	*190.95 FS
17	1		*REAR NUMBER PLATE	Dented	20.00 FS	*20.00 FS
18	1		*STICKER - 70KM/H	Necessary	10.00 FS	*10.00 FS
19	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
20	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,807.04	5,805.85
- List Item Discount on L Items 25.00/25.00% (\$)	1,545.00	1,336.23
Total Parts (\$)	5,262.04	4,469.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, LOCK ASSY, TAILLAMP, TO CUT, WELD & RENEW REAR END PANEL OUTER, KNOCK & REPAIR REAR FLOOR BOARD PANEL AND REALIGN THE SAME	New	700.00	600.00
3	PUTTY & RESPRAY ON REAR END PANEL, REAR FLOOR BOARD PANEL, TAILGATE, LOWER GARNISH	New	600.00	500.00
4	TO REWRITE ADVERTISEMENT	New	300.00	200.00
Gross Labour Cost (\$\$)			1,700.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >