

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22007634/AVCE2**Date:** 09/12/2022**REFERENCE**

Insured/Claimant:	YUM LIN FOON	Policy No:	2070135153		
Date of Loss:	02/08/2022	Nature of Claim:	OD	Claim No:	2658964047SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV1960C		Engine No:	CZDC00162
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)		Chassis No:	WAUZZZF35L1124327
Reg. Date:	18/09/2020 (Man. Year: 2020)		Odometer:	11985 km
Colour:	Blue			
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$168,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,390.00	6,623.60	2,766.40	29.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	4,702.00	5,650.00	54.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,742.00	11,325.60	8,416.40	42.63
+ GST 7.00/7.00% (S\$)	1,381.94	792.79	589.15	42.63
Nett Amount (S\$)	21,123.94	12,118.39	9,005.55	42.63

INSPECTION

Date of Assignment:	11/08/2022		
Date Inspected:	10/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Dented	3,028.00 FS	*2,422.40 FS
2	1		*REAR DOOR OUTER SEAL - RH	Necessary	151.00 FS	*120.40 FS
3	1		*REAR DOOR CATCH	Not Necessary	134.00 FS	*- FS
4	1		*REAR DOOR COVER - RH	Necessary	368.00 FS	*294.00 FS
5	1		*FRONT DOOR - RH	Dented	3,028.00 FS	*2,422.40 FS
6	1		*FRONT DOOR OUTER SEAL - RH	Necessary	185.00 FS	*147.60 FS
7	1		*FRONT DOOR CATCH	Not Necessary	134.00 FS	*- FS
8	1		*FRONT DOOR COVER - RH	Necessary	390.00 FS	*312.00 FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS
10	2		*REAR WHEEL COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
11	1		*REAR BUMPER INSERT	Not Necessary	107.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
13	1		*REAR WHEEL HOUSING LINER	Not Necessary	262.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,390.00	6,623.60
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
3	TO DISMANTLE AND REINSTAL REAR BUMPER. TO REPAIR RHS REAR FENDER. TO RENEW RHS REAR DOOR AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	1,500.00
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, 2 DOOR COVERS AND BOTH REAR WHEEL ARCH TRIMS	New	5,500.00	2,450.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	10,352.00
				4,702.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >