

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007638/EQY3Q2**Date:** 30/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00109802200

Claimant Vehicle No : GBD5275X **Insured Vehicle No :** SMZ7910L

Date of Loss: 26/07/2022 Nature of Claim: TP Claim No: SNM22D205210/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD5275X**

Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KD2446072

Reg. Date: 24/11/2014 (Man. Year: 2014) Chassis No: JTFHT02P400151130

Colour: Blue Odometer: 235209 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,954.00	1,329.00	625.00	31.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	780.00	450.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,184.00	2,109.00	1,075.00	33.76
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	3,184.00	1,700.00	1,484.00	46.61
+ GST 7.00/7.00% (\$\$)	222.88	119.00	103.88	46.61
Nett Amount (\$\$)	3,406.88	1,819.00	1,587.88	46.61

INSPECTION

Date of Assignment: 11/08/2022

Date Inspected: 12/08/2022 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Nov 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD5275X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crushed	420.00 FL	*420.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	252.00 FL	*252.00 FL
3	1		*FRONT BUMPER BEAM	Repair	270.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER	Broken	108.00 FL	*108.00 FL
5	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
6	1		*FRONT GRILLE	Cut	432.00 FL	*432.00 FL
7	1		*HEADLAMP LH	Broken	530.00 FL	*530.00 FL
8	1		*HEADLAMP BRACKET LH	Not Necessary	30.00 FL	*- FL
9	1		*A PILLAR LH (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
11	1		*ADVERTISEMENT STICKER	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,472.00	1,772.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	518.00	443.00
Total Parts (\$\$)	1,954.00	1,329.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	600.00	350.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	400.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$)			1,230.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >