

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22007657/UCY3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : PC1242G**Insured Vehicle No :** GBJ9714M

Date of Loss: 05/08/2022

Nature of Claim: TP

Claim No: 2022 22006019FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PC1242G**

Make & Model: TOYOTA HIACE, 3.0 (A)

Engine No: 1KD2150045

Reg. Date: 28/02/2012 (Man. Year: 2012)

Chassis No: JTFST22P100013062

Colour: White

Odometer: 791801 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,591.28	940.87	4,650.41	83.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,070.00	930.00	46.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,591.28	2,010.87	5,580.41	73.51
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	7,591.28	1,800.00	5,791.28	76.29
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 11/08/2022

Date Inspected: 24/08/2022 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49 Synergy@KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC1242G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAILLAMPS	Not Necessary	850.00 FL	*- FL
2	2		*REAR TAILLAMP LOWER GARNISHES	Not Necessary	568.40 FL	*- FL
3	1		*REAR END PANEL	Repair	569.10 FL	*- FL
4	1		*REAR INNER MEMBER	Repair	624.50 FL	*- FL
5	1		*REAR END PANEL TOP MOULDING	Not Necessary	259.36 FL	*- FL
6	1		*REAR BUMPER	Deformed / Torn	738.00 FL	*586.10 FL
7	2		*REAR BUMPER TOP BRACKETS	Not Necessary	130.00 FL	*- FL
8	3		*REAR BUMPER LOWER BRACKETS	Bent	156.00 FL	*156.00 FL
9	1		*REAR BUMPER REINFORCEMENT	No such part	458.00 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINERS	Cracked	112.40 FL	*112.40 FL
11	1		*REAR FLOOR PANEL	Not Necessary	1,880.80 FL	*- FL
12	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	486.95 FL	*- FL
13	1		*REAR SPARE TYRE LOCK CATCH	Not Necessary	88.20 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
15	1		*SET REAR REVERSE SENSOR (4 PCS)	Shorted	350.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,321.71	1,154.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,730.43	213.63
Total Parts (\$\$)	5,591.28	940.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	450.00
2	TO RESPRAY PAINTING ON AFFECTED AREAS	New	800.00	580.00
3	TO APPLY UNDERCOATING	New	150.00	0.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	40.00
5	TO REMOVE ,REPLACE DAMAGED LAMP AND CHECK REAR WIRING	New	100.00	0.00
Gross Labour Cost (\$\$)			2,000.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >