

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: DM21HO00513 Date: 22nd Sep 2022

Our Ref: CS1/EQI22007661/Eqy3e2

M/s EQ Insurance Company LTD

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XD 1865J

INSURED VEHICLE: YN 3064B ACCIDENT DATE: 03/04/2021

We thank you for your instruction on 11/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XD 1865J from M/s Kelvin Automotive Appraising Services.
- b) Singapore Accident Statement of Vehicles XD 1865J and YN 3064B.
- c) Colour damaged vehicle photographs of XD 1865J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : XD 1865J

Make & Model : Nissan GKB45CLBHNB

Chassis Number : GKB4CLB00171

Year of Registration : 2007 Engine Capacity : 13074 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.