

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007665/ENY3Q2**Date:** 30/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00078762201

Claimant Vehicle No : SMU4161C **Insured Vehicle No :** SLJ2469Z

Date of Loss: 21/07/2022 Nature of Claim: TP Claim No: SNM22D205423/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU4161C**

Make & Model: MITSUBISHI SPACE STAR, 1.2 (A) Engine No: 3A92UJX0477

Reg. Date: 13/08/2020 (Man. Year: 2020) Chassis No: MMBXTA03AMH000287

Colour: Grey Odometer: 18582 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	775.00	618.00	157.00	20.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,670.00	2,680.00	61.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,125.00	2,288.00	2,837.00	55.36
+ GST 7.00/7.00% (S\$)	358.75	160.16	198.59	55.36
Nett Amount (S\$)	5,483.75	2,448.16	3,035.59	55.36

INSPECTION

Date of Assignment: 12/08/2022

Date Inspected: 05/08/2022 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2022)
Parts:	143	mitsubishi space star 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4161C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FACE ,RR BUMPER	Broken	598.00 FS	*598.00 FS
3	1		*BRACKET ,RR BUMPER SIDE ,LH	Not Necessary	10.00 FS	*- FS
4	1		*BRACKET ,RR BUMPER	Not Necessary	69.00 FS	*- FS
5	1		*REFLECTOR ,LH	Not Necessary	48.00 FS	*- FS
Total Parts (S\$)						775.00 618.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER PANEL & AFFECTED AREA REPAIR ON REAR LH FENDER	New	1,920.00	640.00
2	PAINT WORK ON REAR BUMPER & REAR LH FENDER	New	1,650.00	550.00
3	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	150.00	80.00
4	PERFORM RUST PREVENTION	New	100.00	0.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	100.00	0.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	150.00	120.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
Gross Labour Cost (\$\$)			4,350.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >