



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|----------------------------------|-------------------------------------------------------|
| CYCLE & CARRIAGE LEASING PTE LTD | Cust No/Name KC000162/ CYCLE & CARRIAGE LEASING PTE L |
| 239 ALEXANDRA ROAD | Reg No/Reg Date SMU4161C / 13/08/202 |
| SINGAPORE 159930 | Date In/Mileage / 0 |
| Contact No Mobile: 91185739 | Chassis No MMBXTA03AMH000287 |
| | Engine No 3A92UJX0477 |
| | Make/Model MIT/21MY SPACE STAR 1.2 CVT (E12) |
| | Colour/Trim U01 TITANIUM GREY M/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|------------------------------------------------------------|-------|-------------------|-----|-------------------|------------|-------|---------------|
| CSM00041 | Cash | 30/07/2022/ 09:48 | TLK | 282 / Kevin Leong | 25732 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | 640 / 1920.00 |
| REPLACE REAR BUMPER PANEL & AFFECTED AREA | | | | | | | |
| REPAIR ON REAR LH FENDER | | | | | | | |
| E PNT98000 | | | | | | | 550 / 1650.00 |
| PAINT WORK ON REAR BUMPER & REAR LH FENDER | | | | | | | 80 / 150.00 |
| E PNT88000 | | | | | | | X 100.00 |
| REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR | | | | | | | X 100.00 |
| M SUNDRY | | | | | | | X 100.00 |
| PERFORM RUST PREVENTION | | | | | | | |
| M SUNDRY | | | | | | | 120 / 150.00 |
| TO APPLY SEALANT ON AFFECTED AREA | | | | | | | 280.00 |
| A 54900099 | | | | | | | |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | |
| A 10028901 | | | | | | | 20 / 50.00 |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | |
| M SUNDRY | | | | | | | |
| SUNDRIES | | | | 1.00 | 598.00 | 00.00 | 598.00 |
| M FACE,RR BUMPER | | | | 1.00 | 10.00 | 00.00 | 10.00 |
| M BRACKET,RR BUMPER SIDE,LH | | | | 1.00 | 69.00 | 00.00 | 69.00 |
| M BRACKET,RR BUMPER | | | | 1.00 | 48.00 | 00.00 | 48.00 |
| M REFLECTOR,LH | | | | | | | |

Estimate

Steve (LKK)
5/8/22, 9.30am

0 WIL N
P/P
4 BL 7
3 Lys

Confirm & accepted by

7% GST on Net 5,125.00 358.75

Total Payable 5,483.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.