



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 9256G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	FRONT FENDER SIDE COVER -SILVER (CONSISTENT)	CUT	165.00	118.00
1	FORK INNER TUBES -R/H (CONSISTENT)	BENT / DAMAGED	520.00	420.00
1	FORK INNER TUBES -L/H (CONSISTENT)	NOT NECESSARY	520.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	285.00	-
1	HANDLE -BAR (CONSISTENT)	BENT	280.00	245.00
1	HANDLE -BAR ENDS (O/S)(CONSISTENT)	SCRATCHED	120.00	38.00
1	SET HAND-GRIP (CONSISTENT)	NOT NECESSARY	80.00	-
1	HEADLAMP (LED)(CONSISTENT)	CRACKED	980.00	950.00
1	METER ASSY (CONSISTENT)	CRACKED	850.00	760.00
1	THROTTLE CABLE (CONSISTENT)	CUT	205.00	205.00
2	SIDE MIRRORS (CONSISTENT)	O/S CUT	150.00	60.00
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	82.00	82.00
1	FRONT SIGNALS(CONSISTENT)	CUT	185.00	115.00
1	FUEL TANK LOWER COVER (SILVER)(CONSISTENT)	CUT	180.00	180.00
2	FRONT FOOTRESTS(CONSISTENT)	O/S CUT	150.00	75.00
2	FRONT FOOTREST BRACKET (CONSISTENT)	O/S CRACKED	260.00	130.00
1	BRAKE PEDAL (CONSISTENT)	BENT	150.00	120.00
1	EXHAUST ASSY (CONSISTENT)	CUT / DAMAGED	950.00	950.00
1	EXHAUST PROTECTOR (CONSISTENT)	CUT	175.00	80.00
	LESS 10% DISCOUNT		-653.70	-452.80
			5,883.30	4,075.20
<b>SPECIAL NETT ITEMS</b>				
1	NUMBER PLATE (FRT) (SN)(CONSISTENT)	SCRATCHED	38.00	10.00
2	FORK OILS (SN)(CONSISTENT)	O/S NECESSARY	30.00	15.00
2	FORK OIL SEALS (SN)(CONSISTENT)	O/S NECESSARY	56.00	28.00
1	SET STEERING CONE (SN)(CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR BOX (SN)(CONSISTENT)	CUT	420.00	300.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX BRACKET (SN)(CONSISTENT)	NOT NECESSARY	180.00	-
			874.00	353.00
	<b>LABOUR</b>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR .INCLUSIVE OF THE REPAIR OF FRONT FENDER .		450.00	300.00
			1,010.00	300.00
	<b>GRAND TOTAL</b>		<b>7,767.30</b>	<b>4,728.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,700.00</b>

Report Ref No. CC4/ASM22007670/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.