

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007673/UQY3Q2**Date:** 29/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00008282200
<b>Claimant Vehicle No :</b>	SKL6397Y	<b>Insured Vehicle No :</b>	SLX8995H
Date of Loss:	11/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D205609/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKL6397Y</b>	Engine No:	2ARE756983
Make & Model:	LEXUS ES250, 2.5 (A)	Chassis No:	JTHBJ1GG902036965
Reg. Date:	06/12/2013 (Man. Year: 2013)	Odometer:	134421 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,962.34	4,376.48	5,585.86	56.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,510.00	950.00	38.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,422.34</b>	<b>5,886.48</b>	<b>6,535.86</b>	<b>52.61</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,700.00</b>		
<b>Nett Amount (\$\$)</b>	<b>12,422.34</b>	<b>4,700.00</b>	<b>7,722.34</b>	<b>62.16</b>

**INSPECTION**

Date of Assignment:	18/08/2022		
Date Inspected:	12/08/2022	Inspected At:	TK LEE AUTOMOTIVE PTE LTD (HQ) 1 Kaki Bukit Ave 6, Autobay,, #02-47 Singapore 417883
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2022)
<b>Parts:</b>	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKL6397Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,015.10 FN	*1,015.10 FN
2	4		*REAR BUMPER PDC SENSOR	Shorted (2 PCS ONLY)	2,036.40 FN	*1,018.20 FN
3	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	89.92 FN	*- FN
4	1		*REAR BUMPER SPONGE	Torn	230.50 FN	*230.50 FN
5	1		*REAR BUMPER REINFORCEMENT	Repair	861.43 FN	*- FN
6	1		*REAR BUMPER SIDE HOLDER -RH /LH	O/S Bent	128.86 FN	*64.43 FN
7	1		*REAR BUMPER SIDE RETAINER -RH /LH	O/S Bent	202.50 FN	*101.25 FN
8	1		*REAR BOOT LID	Repair	981.62 FN	*- FN
9	1		*REAR BOOT LOGO	Not Necessary	92.60 FN	*- FN
10	1		*REAR BOOT EMBLEM LEXUS	Not Necessary	110.25 FN	*- FN
11	1		*REAR BOOT EMBLEM ES250	Not Necessary	110.25 FN	*- FN
12	2		*REAR BOOT LAMPS	Not Necessary	763.86 FN	*- FN
13	1		*REAR BOOT INNER LOCK	Not Necessary	566.95 FN	*- FN
14	1		*REAR BOOT W/STRIP	Necessary	299.42 FN	*299.42 FN
15	1		*REAR END PANEL	Dented	869.10 FN	*869.10 FN
16	1		*REAR END PANEL GARNISH	Twisted	361.43 FN	*361.43 FN
17	1		*REAR EXHAUST SILENCER -RH	Not Necessary	1,055.60 FN	*- FN
18	1		*REAR EXHAUST CHROME PIPE	Not Necessary	190.65 FN	*- FN
19	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	199.50 FN	*- FN
20	1		*REAR TAILLAMP -RH	Cracked	581.93 FN	*581.93 FN
21	1		*REAR UNDERCOVER	Deformed	221.40 FN	*221.40 FN
22	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
23	1		*SET REAR UNDERCOVER CLIP	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>11,059.27</b>	<b>4,852.76</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	1,096.93	476.28
<b>Total Parts (S\$)</b>	<b>9,962.34</b>	<b>4,376.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TO REMOVE & REPLACE EXHAUST SYSTEM	New	100.00	0.00
4	TO TUFF KOTE	New	60.00	30.00
5	TO PUTTY ,SRPAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	800.00
6	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS	New	1,050.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,460.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >