

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007675/KNY3Q2**Date:** 13/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00056682200		
Claimant Vehicle No :	SME4546K	Insured Vehicle No :	GY5060D		
Date of Loss:	10/08/2022	Nature of Claim:	TP	Claim No:	SNM22D205595/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4546K	Engine No:	LEB6445818
Make & Model:	HONDA GRACE HYBRID, 1.5 DX (A)	Chassis No:	GM41205797
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	112542 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Bridgestone 2 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Bridgestone 2 mm	Rear Right Side:	Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,743.00	4,557.60	2,185.40	32.41
Miscellaneous Items	915.00	745.00	170.00	18.58
Labour	5,370.00	4,410.00	960.00	17.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,028.00	9,712.60	3,315.40	25.45
Approved Total (Overridden) (\$\$)		9,700.00		
(\$\$)	13,028.00	9,700.00	3,328.00	25.54
+ GST 7.00/7.00% (\$\$)	911.96	679.00	232.96	25.54
Nett Amount (\$\$)	13,939.96	10,379.00	3,560.96	25.54

INSPECTION

Date of Assignment:	12/08/2022	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	12/08/2022	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	143	HONDA GRACE HYBRID 1.5 DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME4546K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Bent	240.00 F	*240.00 FL
2	1		*2 PCS REAR BUMPER RETAINERS @12/PC	Cracked	24.00 F	*24.00 FL
3	1		*8 PCS REAR BUMPER CLIPS @2/PC	Necessary	16.00 F	*16.00 FL
4	1		*1 PC REAR BUMPER LOWER GARNISH	Bent	23.00 F	*23.00 FL
5	1		*1 PC REAR BUMPER UNDER LOWER COVER	Cracked	90.00 F	*90.00 FL
6	1		*2 PCS REAR BUMPER REFLECTOR GARNISHS @15/PC	Dented / Distorted	30.00 F	*30.00 FL
7	1		*1 PC REAR BUMPER REINFORCEMENT	Repair	230.00 F	*- FL
8	1		*1 PC BOOTLID	Bent	620.00 F	*620.00 FL
9	1		*2 PCS BOOTLID HINGES @43/PC	Bent	86.00 F	*86.00 FL
10	1		*1 PC BOOTLID UPPER LOCK	Dented	65.00 F	*65.00 FL
11	1		*1 PC BOOTLID LOWER LOCK CATCH	Repair	22.00 F	*- FL
12	1		*1 PC BOOTLID CENTRE GARNISH	Cracked	95.00 F	*95.00 FL
13	1		*1 PC BOOTLID EMBLEM (H)	Necessary	18.00 F	*18.00 FL
14	1		*1 PC BOOTLID EMBLEM (GRACE)	Necessary	28.00 F	*28.00 FL
15	1		*1 PC BOOTLID EMBLEM (HYBRID)	Necessary	38.00 F	*38.00 FL
16	1		*1 PC BOOTLID LH REFLECTOR	Cracked	245.00 F	*245.00 FL
17	1		*1 PC BOOTLID RH REFLECTOR	Cracked	245.00 F	*245.00 FL
18	1		*1 PC BOOTLID UPPER SPOILER	Cracked	350.00 F	*350.00 FL
19	1		*1 PC BOOTLID UPPER SPOILER 3RD BRAKE LAMP	Cracked	135.00 F	*135.00 FL
20	1		*2 PCS REAR NUMBER PLATE LAMPS @32/PC	Serviceable	64.00 F	*- FL
21	1		*1 PC BOOTLID WEATHER STRIP	Cut	58.00 F	*58.00 FL
22	1		*1 PC BOOTLID INNER TRIM	Dented	60.00 F	*60.00 FL
23	1		*8 PCS BOOTLID INNER TRIM CLIPS @2/PC	Necessary	16.00 F	*16.00 FL
24	1		*1 PC BOOTLID RH REAR FENDER	Buckled	490.00 F	*490.00 FL
25	1		*1 PC BOOTLID LH TAILLAMP	Cracked	260.00 F	*260.00 FL
26	1		*1 PC BOOTLID RH TAILLAMP	Cracked	260.00 F	*260.00 FL
27	1		*1 PC BOOTLID LH TAILLAMP PANEL	Bent	75.00 F	*75.00 FL
28	1		*1 PC BOOTLID RH TAILLAMP PANEL	Bent	75.00 F	*75.00 FL
29	1		*1 PC REAR END PANEL	Bent	280.00 F	*280.00 FL
30	1		*4 PCS REAR END PANEL INNER TRIM CLIPS @2/PC	Necessary	8.00 F	*8.00 FL
31	1		*1 PC REAR FLOOR PAN	Bent	480.00 F	*480.00 FL
32	1		*1 PC REAR FLOOR TOP COVER BOARD	Deformed	180.00 F	*180.00 FL
33	1		*1 PC REAR TOOL TRAY	Dented	85.00 F	*85.00 FL
34	1		*1 PC JACK	Bent	160.00 F	*160.00 FL
35	1		*8 PCS REAR FENDER INNER GARNISH CLIPS @2/PC	Necessary	16.00 F	*16.00 FL
36	1		*1 PC REAR WINDSCREEN GLASS	Serviceable	730.00 F	*- FL
37	1		*1 SET REAR WINDSCREEN GLASS MOULDING	Necessary	60.00 F	*60.00 FL
38	1		*2 PCS REAR FENDER INNER GARNISHS @160/PC	Distorted	320.00 F	*320.00 FL
39	1		*1 PC REAR EXHAUST MUFFLER	Bent	390.00 F	*390.00 FL
40	1		*2PCS REAR EXHAUST MUFFLER MOUNTING @25/PC	Torn	50.00 F	*50.00 FL
41	1		*1 PC REAR EXHAUST HEAT SHIELD	Bent	26.00 F	*26.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)6,743.005,697.00

- List Item Discount on L Items 0.00/20.00% (\$\$)0.001,139.40

Total Parts (\$\$)6,743.004,557.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC BODY JOINT SEALANT (NECESSARY)	150.00	90.00
2	1	1 PC REAR EXHAUST EXTENSION PIPE (DENTED)	120.00	60.00
3	1	1 PC REAR NUMBER PLATE (DENTED)	35.00	35.00
4	1	1 PC REAR WINDSCREEN GLASS SEALANT (NECESSARY)	40.00	40.00
5	1	1 PC REVERSE CAMERA (CRACKED)	350.00	300.00
6	1	1 SET REVERSE SENSOR (DENTED)	220.00	220.00
Sub Total (\$\$)			915.00	745.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
3	REMOVE & REFIX SEAT,CARPET, TOP ROOF LINING,ETC	New	120.00	100.00
4	REMOVE & REFIX REAR BUMPER ASSY,REFLECTORS,LOWER SKIRT,TAILLAMPS,REFLECTORS,SPOILER,BOOT,LOCK ASSY,TO CUT,WELD & RENEW REAR PANEL,REAR RH FENDER,REAR COMPARTMENT,TAILLAMP PANELS,TO STRAIGHTEN,KNOCK & REPAIR REAR BOTH CHASSIS,REAR LH FENDER AND REALIGN THE SAME	New	2,500.00	2,200.00
5	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	New	100.00	60.00
6	TO MOUNT ON CAR-O-LINER	New	250.00	0.00
7	PUTTY & RESPRAY ON REAR COMPARTMENT,REAR PANEL,TAILLAMP PANEL,BOOT,HINGES,SPOILER,REAR BOTH FENDERS,REAR BOTH CHASSIS	New	1,800.00	1,500.00
8	TO REMOVE & REFIX SMART KEY SENSOR,BUZZER SENSOR AND CHECK SYSTEM	New	50.00	50.00
9	RUSTPROOFING	New	120.00	100.00
10	TO REMOVE & REFIX HYBRID BATTERY AND REPROGRAMME SYSTEM	New	280.00	250.00
Gross Labour Cost (\$\$)			5,370.00	4,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >