

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22007677/EVY3Q2**Date:** 24/11/2022**REFERENCE**

Insured/Claimant: SEAH KHER CHUAN Policy No: DMPCSNW00257432100

Date of Loss: 02/08/2022

Nature of Claim: OD

Claim No: SNM22D205434/C01/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLR8989H**

Make &amp; Model: BMW 218I, 1.5 (A)

Reg. Date: 29/09/2021 (Man. Year: 2020)

Colour: Red

Engine Capacity: 1499 cc

Market Value/New Car Price: S\$165,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 39846253B38A15F

Chassis No: WBA12AK0207H36866

Odometer: 14059 km

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R17

Front Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Tyre Size: 225/45 R17

Rear Left Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,555.30	3,558.00	2,997.30	45.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,633.00	3,893.00	1,740.00	30.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,188.30</b>	<b>7,451.00</b>	<b>4,737.30</b>	<b>38.87</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	11,688.30	6,951.00	4,737.30	40.53
<b>+ GST 7.00/7.00% (S\$)</b>	818.18	486.57	331.61	40.53
<b>Nett Amount (S\$)</b>	<b>12,506.48</b>	<b>7,437.57</b>	<b>5,068.91</b>	<b>40.53</b>

**INSPECTION**

Date of Assignment: 12/08/2022

Date Inspected: 17/10/2022 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance  
Centre  
Singapore 159941

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2022)
<b>Parts:</b> 143	BMW 218I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLR8989H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 7.5JX17 DOUBLE SPK 548	Not Necessary	996.90 FS	*- FS
3	1		*FRT LH SIDE PANEL	Repair	639.70 FS	*- FS
4	1		*LH FOG LAMP COVER	Cut	47.30 FS	*47.30 FS
5	1		*FRT BUMPER BOTTOM TRIM PANEL	Not Necessary	177.00 FS	*- FS
6	1		*LH AIR INLET FINISHER	Not Necessary	68.95 FS	*- FS
7	1		*LH GRID LATERAL	Broken	80.80 FS	*80.80 FS
8	1		*FRT FLAP TOWING EYE PRIMED	Not Necessary	43.95 FS	*- FS
9	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Not Necessary	929.20 FS	*- FS
10	1		*SET MOUNTING PDC /PMA SENSOR FRT	Not Necessary	71.60 FS	*- FS
11	1		*LH HEADLIGHT LED TECHNOLOGY	Cut	2,399.10 FS	*2,399.10 FS
12	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Dented	950.80 FS	*950.80 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>6,555.30</b>	<b>3,558.00</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER AND FRONT LEFT FENDER	New	2,250.00	1,275.00
2	TO RESPRAY FRONT BUMPER AND LEFT FRONT FENDER	New	1,923.00	1,826.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING	New	177.00	168.00
5	TO REPLACE LEFT HEADLIGHT	New	481.00	456.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	0.00
7	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,893.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >