



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 5331G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	BUCKLED / DENTED		
	REAR BUMPER (CONSISTENT)		1,985.00	1,421.50
	LESS 10% DISCOUNT		-	-142.15
			1,985.00	1,279.35
	<u>SPECIAL NETT ITEMS</u>	NECESSARY		
	SET REAR BUMPER CLIPS (SN) (CONSISTENT)		35.00	35.00
			35.00	35.00
	<u>LABOUR</u>	NOT NECESSARY		
	TO REMOVE ALL DAMAGED PARTS, KNOCK OUT DENTS, JACK OUT DAMAGED PANEL PANEL, ADJUST, REPLACE, RESHAPE, CUT, WELD, REFIX & REALIGN BODY STRUCTURE.		300.00	220.00
	SPRAY PAINTING FOR NEW AND REPAIR PARTS INCLUDING SUPPLY OF PAINTS MATERIALS.		350.00	250.00
	COMPUTER DIAGNOSE TO RESET PARKING SENSOR FALSE MEMORY.		120.00	60.00
	CHECK WIRING, LIGHTING SYSTEM FOR PROPER FUNCTION.		50.00	-
			820.00	530.00
GRAND TOTAL			2,840.00	1,844.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,450.00

Report Ref No. CS/ASM22007685/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.