

ASS. REC. BY:

REF:

ASM/ 2200 7685 / Kn

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1000

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$62k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PKS 5331G

Yr Regn:

04, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mc

A180

c.c

1593

Colour:

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading:

192595

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 17604 22J36 3014

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PRT / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/8/12

D.O.I.

16/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Est not ready

17/8 11/24 8/1450/ Gordon

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ - RS. SI

) Fixing

) Others

Report Format:

ump Sum / I.B.I: (\$

TOTAL

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel : 64810304 Fax : 64815587 Reg No : 200600989K

MSIG Insurance (Singapore) Pte Ltd (SGX Centre)

Motorcar Claim Department

Attn: Claim Officer

Estimate Repair

Date: 16/8/2022

Accident Involving SKS5331G & SH6821R On 11/8/2022

Item	Descriptions	Amount
1	Rear Bumper <i>1421.50</i>	\$ 1,985.00 ✓
<i>100</i> Total For Parts		\$ 1,985.00

S/N Item (s)

1	Rear Bumper Clips - 1 Set	\$ 35.00 ✓
Total For S/N		\$ 35.00

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	
	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 300.00 <i>2201</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 350.00 <i>2501</i>
3	Computer Diagnose To Reset Parking Sensor False Memory	\$ 120.00 <i>601</i>
4	Check Wiring, Lighting System For Proper Function	\$ <i>~</i> 50.00 <i>X</i>
		\$ 820.00

Ready Auto Care Pte Ltd

Total For Parts & Labour \$ 2,840.00

No Of Days For Repair 3 Days

Not Authorized
11 Sep 8145 dh
Money After Paint
2 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: