



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 5070U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH SIDE MIRROR COVER (CONSISTENT)	CRACKED	55.50	55.50
1	FRONT RH SIDE MIRROR BODY (CONSISTENT)	BROKEN	540.00	540.00
1	FRONT RH 1/4 GLASS (CONSISTENT)	CUT	290.00	290.00
1	FRONT RH 1/4 GLASS MOULDING (CONSISTENT)	NECESSARY	55.00	55.00
1	FRONT RH DOOR BLACK STICKER (CONSISTENT)	NECESSARY	38.80	38.80
1	FRONT RH DOOR WEATHERSTRIP (CONSISTENT)	SERVICEABLE	145.00	-
	LESS 20% DISCOUNT		-224.86	-195.86
			899.44	783.44
1	FRONT RH 1/4 GLASS INNER SEAL (SN)(CONSISTENT)	NECESSARY	45.00	30.00
	LESS 20% DISCOUNT		-9.00	-
			36.00	30.00
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES .		600.00	100.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES .		600.00	400.00
	TO CHECK WIRING .		30.00	20.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	50.00	-
			1,280.00	520.00
	GRAND TOTAL		2,215.44	1,333.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,050.00

Report Ref No. CC4/ASM22007687/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.