

ASS. REC. BY:

REF:

ASM/ 220076871K

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 62k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 5070U Yr Regn: 12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle c.c. 1498

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 379748 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GKR 1100294

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/8/22

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 15/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fr old door minor

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/8 11:30pm @ 1050h Car Park

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SLJ5070U

No.	Qty	List Items	
1	1	Front RH side mirror cover	\$ CM 55.50 ✓
2	1	Front RH side mirror body	\$ Br 540.00 ✓
3	1	Front RH 1/4 glass	\$ W 290.00 ✓
4	1	Front RH 1/4 glass moulding	\$ M 55.00 ✓
5	1	Front RH 1/4 glass inner seal	\$ M 45.00 30% ✓
6	1	Front RH door black sticker	\$ M 38.80 ✓
7	1	Front RH door weatherstrip	\$ R 145.00 X
			\$ 1,169.30
Less 20%			\$ 233.86
Total :			\$ 935.44

	Labour	
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 600.00 100% ✓
2	To putty and spray Spray Paintings charges.	\$ 600.00 400% ✓
3	To check wirings.	\$ 30.00 20% ✓
4	To supply and apply anti rust treatment	\$ M 50.00 X
Total :		\$ 1,280.00

Total Parts and Labour : \$ 2,215.44

Not Withheld
11pm @ 1050h
Pickup After Repair
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: